



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR June 26 2012	REPORT TIME 9:00 am	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH - DAY - YEAR June 26 2012	OCCURRENCE TIME 7:00 am		
C	LAND USE PERMIT NUMBER (IF APPLICABLE) N2011C0009	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-JER1119		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Jericho Mine Site		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 66 MINUTES 01 SECONDS 00		LONGITUDE DEGREES 111 MINUTES 27 SECONDS 00	
F	RESPONSIBLE PARTY OR VESSEL NAME Shear Diamonds	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION 6 Adelaide St. E., Suite 220, Toronto, ON		
G	ANY CONTRACTOR INVOLVED no	CONTRACTOR ADDRESS OR OFFICE LOCATION n/a		
H	PRODUCT SPILLED diesel	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 20L	U.N. NUMBER 1202	
	SECOND PRODUCT SPILLED (IF APPLICABLE) none	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES n/a	U.N. NUMBER n/a	
I	SPILL SOURCE fuel truck	SPILL CAUSE nozzle malfunction	AREA OF CONTAMINATION IN SQUARE METRES 2	
J	FACTORS AFFECTING SPILL OR RECOVERY none	DESCRIBE ANY ASSISTANCE REQUIRED n/a	HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT n/a	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS -this spill is being reported in accordance with the conditions outlined in Part H, Section 8(b) of Shear Diamonds Water Board (NWB) Licence 2AM-JER1119 pursuant to the Nunavut Waters and Nunavut Surface Rights Tribunal Act and as required by the Government of Nunavut's Environmental Protection Act paragraph 5.1(a) -this incident occurred approximately 500m northwest of Ash Lake -while fueling a bobcat the fuel nozzle of the fuel truck got stuck in the on position and diesel overflowed from the bobcat on to the ground -the nozzle was eventually put back into the off position -the bobcat was used to shovel the contaminated dirt into drums which will be placed in the HWTA -a lock was put on the fuel truck nozzle and will not be used until it can be replaced			
L	REPORTED TO SPILL LINE BY Wes Atchison	POSITION Environmental Tech.	EMPLOYER Shear Diamonds	LOCATION CALLING FROM Jericho Mine Site TELEPHONE 778-372-2723
M	ANY ALTERNATE CONTACT Andy Uyarrai	POSITION Site Services Manager	EMPLOYER Shear Diamonds	ALTERNATE CONTACT Jericho Mine Site ALTERNATE TELEPHONE 778-372-2750
REPORT LINE USE ONLY				
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN	
AGENCY		CONTACT NAME	CONTACT TIME	FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
LEAD AGENCY				
FIRST SUPPORT AGENCY				
SECOND SUPPORT AGENCY				
THIRD SUPPORT AGENCY				