



Indian and Northern
Affairs Canada

Affaires indiennes
et du Nord Canada

INDUSTRIAL WATER USE INSPECTION REPORT

DATE: July 20/05COMPANY REP.: Cheryl Wray / Robert JonesLICENSEE: Bonheur Resources / TaharaLICENCE #: NWS-TERO-110

WATER SUPPLY

Source: Cont LakeQuantity Used: Not Known

Meter Rdg.: _____

Indicate: **A - Acceptable****U - Unacceptable****N/A - Not Applicable**Intake Facilities _____
Flow Meas. Device _____Storage Structures _____
Conveyance Lines _____Treatment Systems _____
Pumping Stations _____Recycling _____
Modifications _____

Comments: Water samples taken from gravity tank before treatment. Water was measured by truckloads. The treatment plant is brand new, clean & apparently well maintained. (N/A) Will need to monitor flow & total chlorine

WASTE DISPOSAL

Tailings: NATailings Pond ☐Natural Lake ☐Underground ☐

Sewage: _____

Sewage Treat. System ☒
Continuous Discharge ☐Tailings Pond ☐
Inter. Dischg. ☒Natural Water Body ☒

Solid Waste: _____

Open Dump ☐Landfill ☐Burn & Bury ☐Till Dump
Underground ☒Indicate: **A - Acceptable****U - Unacceptable****N/A - Not Applicable**Discharge Quality NA
Decant Structures NA
Dyke Inspections NAConveyance Lines NA
Pond Treatment NA
Runoff Diversion ADisch. Meas. Dev. U
Dams, Dykes NA
Erosion NAFree board NA
Seepage NA
Spill: A

Effluent Discharge Rate: _____

Samples Collected: _____

Comments: Event / metal waste is being in the till dump until a landfill can be constructed. Hays is coming up to handle hazardous waste on site & transport it south to Superfund. Average effluent discharge was sampled. A new flow meter is on order as the old one malfunctioned. New gauge not well.

GENERAL CONDITIONS

Indicate: **A - Acceptable****U - Unacceptable****N/A - Not Applicable**Ore & Waste Rock Stockpiles _____
Geotechnical Inspection _____
Restoration Activities _____
Mine Water Discharge _____Records & Reporting _____
Posting, Signage _____
New Construction _____
Chemical Storage _____Surv. Net. Prog. _____
Contingency Plan _____
Fuel Storage _____
Annual Report _____

Comments: Back pass under construction. Transit filling station under improved grill containment but tanks have gone up quickly. Hays on task from to be completed. Starting next week. A pump in the pit is used to collect water from pit then pump the

Violations of Act or Licence: No violation of the Act or Licence were observed in the course of the inspection. Monitoring is required for the freshwater intake & the sewage outfall. These systems are on order according to Cheryl & Robert. Operation of the site is greatly improved since last year.

General Comments: A dump truck hauler was for composting (land) as was observed. The landfill with a synthetic liner is under construction at the waste oil storage site. The waste oil storage area appears to be well kept & maintained than in previous years.

Page 2 attached ☐ Yes ☐ No

2 Environmental
Licensee Representative's Title

Scott Stewart
Inspector's Name

Cheryl Wray
Licensee Representative's Signature

Scott Stewart
Inspector's Signature