

Memo

To:	Karyn Lewis, LMI	Client:	Lupin Mine Inc.
From:	Alvin Tong	Project No:	1CL008.002
Cc:	Patrick Downey	Date:	September 3, 2015
Subject:	August 2015 Sewage Facility Geotechnical Inspection		

August 2015 Geotechnical Inspection

SRK engineer, Alvin Tong, has completed a geotechnical inspection of the Lupin Mine on 2 August, 2015. This inspection indicated that repairs have been completed in the lower dam, according to the recommendations provided in the geotechnical report (SRK 2014). It was noted during the inspection that LMI had set up syphons to drop the water level on the lower sewage pond. A technical memorandum was issued on 6 August, 2015 (SRK 2015), to confirm the "Measures to be Taken". Action item 2a) in the 22 July, 2015 Inspector's Directive has been substantially completed with minor finishing work scheduled to be completed before the end of 2015's field season.

Mr. Tong completed an additional geotechnical inspection in 19 August, 2015. It was noted in this inspection that the lower sewage pond had been lowered to provide 1.4 m of freeboard before syphoning was completed on 19 August, 2015. The upper sewage dam was noted to have 1.1 m of freeboard. The dams met the minimum freeboard to allow operation. LMI has provided photographs on 2 September, 2015 indicating all finishing work on both dams are completed.

SRK Consulting (Canada) Inc.



Alvin Tong, PEng
Senior Consultant

Disclaimer—SRK Consulting (Canada) Inc. has prepared this document for Lupin Mine Inc.. Any use or decisions by which a third party makes of this document are the responsibility of such third parties. In no circumstance does SRK accept any consequential liability arising from commercial decisions or actions resulting from the use of this report by a third party.

The opinions expressed in this report have been based on the information available to SRK at the time of preparation. SRK has exercised all due care in reviewing information supplied by others for use on this project. Whilst SRK has compared key supplied data with expected values, the accuracy of the results and conclusions from the review are entirely reliant on the accuracy and completeness of the supplied data. SRK does not accept responsibility for any errors or omissions in the supplied information, except to the extent that SRK was hired to verify the data.

1 **References**

SRK 2014, 2014 Sewage Pond Dams Geotechnical Inspection. Report submitted to LMI, October 2014.

SRK 2015, Letter RE: Inspector's Direction Issued on July 22, 2015. Letter submitted to LMI, August 6, 2015.