

∩∩%b%δ%₺ P.O. Box 340 b∿ቦ%ሮታ%, ൧௳ഊ Rankin Inlet, Nunavut XOCOGO

TO: Richard Dwyer

LICENCE: 2AM-MEA1530

DATE: 27 February 2023

ሳየልሳየ Arviat

SUBJECT: KIA comments on the Baker Lake Water Management Improvement

%Locod%

Baker Lake

Dear Mr. Dwyer,

water flow.

 Δ^{μ} \rightarrow C^{η}

Chesterfield Inlet The Kivalliq Inuit Association (KIA) has completed a technical review of Agnico Eagle Mines Limited's (AEM) "Baker Lake Water Management Improvement", which is related to Meadowbank Type A water license 2AM-MEA1530.

The KIA has the following comments:

4-6-56

Coral Harbour

۰۵۶۹

Naujaat

_Б«րութագու

Rankin Inlet

2) Material Quantities – The KIA requests that the non-ARD source location(s) of the materials be shown by diagram(s).

1) Permafrost – The permafrost parameters used are based on thermistors that are installed at

the Meadowbank mine site. The Baker Lake Marshalling Area currently has no thermistors and is in close proximity to a significant water body, Baker Lake. The KIA recommends that several thermistors be installed that can monitor the permafrost depth. This would allow

monitoring of the active layer in order to better mitigate any potential erosion of the water management infrastructure related to variable permafrost depths and changes in seasonal

U6224Q20

Whale Cove

3) Dust Management – The KIA requests that the dust control procedures be included for the transporting and dumping of all the material quantities.

4) Community – The KIA requests that the tentative schedule, route(s) through the community of Baker Lake, number of trucks and size of trucks be provided.



∩∩⁵⁶b⁵b⁵6 ℃ P.O. Box 340 ხ°Ր% ்ெ ውር የ Rankin Inlet, Nunavut X0C0G0

The KIA appreciates the opportunity to review this information.

Regards

Director of Lands

Kivalliq Inuit Association

