



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR April 17, 2012		REPORT TIME 16:50		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR April 17, 2012		OCCURRENCE TIME 05:45			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL BL-14			WATER LICENCE NUMBER (IF APPLICABLE) NWA-2AM-MEA0815		
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 65 MINUTES 01 SECONDS 33			LONGITUDE DEGREES 96 MINUTES 04 SECONDS 01		
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO-EAGLE MINES		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0X 0A0			
G	ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED DIESEL		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 410 LITERS		U.N. NUMBER 1202	
	SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER	
I	SPILL SOURCE FUEL LINE		SPILL CAUSE SPLIT LINE		AREA OF CONTAMINATION IN SQUARE METRES 95	
J	FACTORS AFFECTING SPILL OR RECOVERY SPILL SPREAD BY WATER		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT	
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS Inside a generator building, a split fuel line caused a leak of diesel fuel. The diesel fuel pooled enough inside the room to cause the wiring at the base of the genset to short out and ignite into flame. Fire alarm went off, fire sprinkler system went off, and ERT team responded. Fuel had spilt out of the building, and with the water from the sprinkler system more diesel spilt out. Diesel spilt outside was mixed with snow. Contaminated snow will be removed and taken to Quarry 22 for storage.					
L	REPORTED TO SPILL LINE BY Jeffrey Pratt		POSITION Environmental Coordi.		EMPLOYER Agnico-Eagle Mines	
M	ANY ALTERNATE CONTACT Stephane Robert		POSITION Environmental Superi.		EMPLOYER Agnico-Eagle Mines	
					ALTERNATE CONTACT Meadowbank	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR		EMPLOYER	
					LOCATION CALLED YELLOWKNIFE, NT	
					REPORT LINE NUMBER (867) 920-8130	
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC				SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME		CONTACT TIME		REMARKS
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						