



Canada

## NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

<b>A</b>	REPORT DATE: MONTH – DAY – YEAR <b>July-16-2014</b>	REPORT TIME <b>09:30</b>	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
<b>B</b>	OCCURRENCE DATE: MONTH – DAY – YEAR <b>July-15-2014</b>	OCCURRENCE TIME <b>10:00</b>			
<b>C</b>	LAND USE PERMIT NUMBER (IF APPLICABLE) <b>KIOL-BL-14</b>	WATER LICENCE NUMBER (IF APPLICABLE) <b>NWA-2AM-MEA0815</b>			
<b>D</b>	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION <b>MEADOWBANK MINE SITE</b>		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
<b>E</b>	LATITUDE DEGREES <b>65</b> MINUTES <b>01</b> SECONDS <b>19</b>		LONGITUDE DEGREES <b>96</b> MINUTES <b>04</b> SECONDS <b>07</b>		
<b>F</b>	RESPONSIBLE PARTY OR VESSEL NAME <b>AGNICO EAGLE MINES LTD</b>	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION <b>BAKER LAKE X0X 0A0</b>			
<b>G</b>	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
<b>H</b>	PRODUCT SPILLED <b>Tailings Slurry</b>	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES <b>~1 m3</b>	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
<b>I</b>	SPILL SOURCE <b>Pipeline</b>	SPILL CAUSE <b>Broken pipeline</b>	AREA OF CONTAMINATION IN SQUARE METRES <b>10</b>		
<b>J</b>	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
<b>K</b>	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS <b>Inside the mill, while mill was operating, the tailings line became disconnected. Before being able to completely stop the mill operation the tailings continued to come out of the pipe. The vast majority of the tailings slurry stayed inside the mill. However, the level became high enough that some leaked outside the door of the mill. Site services department immediately commenced clean up of the slurry. Back hoes were used to mix slurry with rock fill. This material was excavated taken to the Tailings Storage Facility.  Photos of clean up and GPS Coordinates will be sent as a follow up.  JEFF PRATT - (867)759-3555 EXTENSION 6728 / RYAN VANENGEN - (867) 763-4610 EXTENSION 6838</b>				
<b>L</b>	REPORTED TO SPILL LINE BY <b>JEFFREY PRATT</b>	POSITION <b>ENVIRO COORDINAT</b>	EMPLOYER <b>AGNICO EAGLE</b>	LOCATION CALLING FROM <b>MEADOWBANK</b>	TELEPHONE <b>8677593555</b>
<b>M</b>	ANY ALTERNATE CONTACT <b>RYAN VANENGEN</b>	POSITION <b>ENVIRO SUPERINT</b>	EMPLOYER <b>AGNICO EAGLE</b>	ALTERNATE CONTACT <b>MEADOWBANK</b> LOCATION	ALTERNATE TELEPHONE <b>8677634610</b>
REPORT LINE USE ONLY					
<b>N</b>	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					