



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR October 11, 2015	REPORT TIME 15:00 CT	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR October 11, 2015	OCCURRENCE TIME 10:30 CT			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KIOL-BL-14	WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-MEA1525			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION MEADOWBANK MINE SITE	REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN			
E	LATITUDE DEGREES 65 MINUTES 2 SECONDS 14	LONGITUDE DEGREES 96 MINUTES 3 SECONDS 58			
F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE XOX 0A0			
G	ANY CONTRACTOR INVOLVED	CONTRACTOR ADDRESS OR OFFICE LOCATION			
H	PRODUCT SPILLED Tailings Slurry	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 500 L	U.N. NUMBER		
	SECOND PRODUCT SPILLED (IF APPLICABLE)	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES	U.N. NUMBER		
I	SPILL SOURCE Tailings discharge pipe	SPILL CAUSE Pipe emptying during clean up	AREA OF CONTAMINATION IN SQUARE METRES 100		
J	FACTORS AFFECTING SPILL OR RECOVERY	DESCRIBE ANY ASSISTANCE REQUIRED	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While switching the tailings deposition point in the North Tailings Cell, a spill of approximately 500L of tailings slurry occurred on RF2 (Rockfill Road 2). After the deposition point change, while unflanging the inactive tailings pipe to complete the pipe clean up, some residual slurry left in the pipe spilled on the road surface. The slurry was confined over the structure and within the tailings facility area. The spill produced and the contaminated material were collected with a loader and put back in the Tailings Storage Facility after the spill occurred. A follow up report will be submitted with the details of the clean up actions. No watercourses are in the vicinity and there was no off site impact or discharge to any receiving watercourses. Spill location : Northing: 7216031 Easting: 638094 Contact information : Erika Voyer 819-759-3555 ext. 6980				
L	REPORTED TO SPILL LINE BY Erika Voyer	POSITION Env. Coordinator	EMPLOYER AGNICO EAGLE	LOCATION CALLING FROM MEADOWBANK	TELEPHONE 7593555x6980
M	ANY ALTERNATE CONTACT Kevin Buck	POSITION Env. Superintendent	EMPLOYER AGNICO EAGLE	ALTERNATE CONTACT MEADOWBANK LOCATION	ALTERNATE TELEPHONE 7593555x6838
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					