

## Remediation

The contaminated ground was collected with loader and was brought to the landfarm. An estimated volume of 24 m<sup>3</sup> was removed.



**Robin Allard**  
**Environmental - Acting Coordinator**  
[robin.allard@agnicoeagle.com](mailto:robin.allard@agnicoeagle.com)

T: 819.759.3555 x6747

Agnico Eagle Mines Limited  
Meadowbank Division  
Baker Lake, Nunavut, Canada  
X0C 0A0

[agnicoeagle.com](http://agnicoeagle.com)

