

## Spill

Upon noticing the drums, warehouse proceeded to empty the c-can to assess if any oil spilled outside. Upon being emptied and moved to the side, some oil was observed on the ground. From the 205 liters capacity of the drums an estimated 150 liters went on the ground with the remaining 55 liters staying inside the c-can.

