

Cause of Spill

The fitting on the line broke because external pressure was being added to the pipe by snow being pushed over from the iron pad towards the discharge line. The sewage was thus discharge closer to the road. This created a change in the path of the flow, resulting in water being observed on the north side.



Broken fitting and pipe



Area of broken line



North side



Snow bank on Stormwater pond