

Corrective measures

A complete investigation was done on site (appendix). Records of maintenance at Arctic Fuel Services were verified. The Pre-operational mandatory check list was filled out by the operator. Root causes identified were: inadequate maintenance and care of trucks (previous welds were identified at the failure area) and load capacity assessment. Corrective measures will include random audits being performed by the Meadowbank maintenance department on Arctic Fuel equipment float. The frequency of the audits will be adjusted with the overall performance and results of the audits.

Closure

This spill, #16-412, was recommended for closure by Christine Wilson, INAC Water Resources officer on December 7th 2016.

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on November 28th, 2016 and the cleanup activities. Please contact the undersigned should you have any questions.



Robin Allard
Environmental Coordinator
robin.allard@agnicoeagle.com
T: 819.759.3555 x6744
Agnico Eagle Mines Limited
Meadowbank Division

AGNICO EAGLE 