



## January 29<sup>th</sup>, 2017 HTR 01 fuel spill

Please find the following information as a follow up to the Spill report submitted January 29th, 2017 by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-MEA1525, Part H, Item 8c.

### Spill Description

After the refueling of the HTR 01, the tanker operator took off the nozzle but fuel came out of the haul truck tank and sprayed on the ground.

There were no off site impact or discharge to any receiving watercourses.

Spill location: Northing: 65'03'46" Easting: 95'59'39"

### Cause of Spill

After investigation, it was observed that the wiggins on the Haul Truck caused the spill.

