

Remediation Actions

Investigation was made to identify the cause of the spill. All wiggins were inspected to avoid a second occurrence and information from the supplier was requested. The area was graded and a loader collected the contaminated soil and brought it to the landfarm.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank on January 29th, 2017 and the cleanup activities. Please contact the undersigned should you have any questions.

A handwritten signature in blue ink, appearing to read 'Martin Theriault', is shown on a light-colored background.

Martin Theriault
Environmental Technician

martin.theriault@agnicoeagle.com
T: 819.759.3555 x6744
Agnico Eagle Mines Limited
Meadowbank Division
Baker Lake, Nunavut, Canada
X0C 0A0