



2025-01-18 MBK 1400L Waste Oil & Coolant – Telehandler

GN reference #: 2025-066

Please find the following information as a follow up to the Spill report submitted January 18th, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector as requested; as due diligence and without prejudice by Agnico Eagle Mines Ltd. and in accordance with the conditions under the Nunavut Water Board License 2AM-MEA1530, Part H, Item 8c.

Spill Description

During operations at Meadowbank, a telehandler was moving a tote into a sea can in the Hazmat area. While storing the tote, the forks from the telehandler punctured three totes containing a mixture of waste oil and coolant.



Spill location(s): 65° 0'57.04"N 96° 4'2.99"W

The spill was within the Operations footprint of Meadowbank. There were no off-site impacts or discharges. Distance to the closest water body is 185m to Third Portage Lake.

Cause of Spill

Human Error

Remediation Actions

The contaminated material was collected and brought to the Meadowbank Tailings Facility



Corrective measures

After completing on investigation on the incident, a review of the procedure for Handling Totes and Barrels with Forked Equipment will be completed by all operators. Disciplinary measures will apply where applicable.

Closure

We trust that the above details described appropriately the spill incident that occurred at the Meadowbank site on January 18th, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Tom Thomson | Environmental Coordinator
tom.thomson@agnicoeagle.com | Direct 819.759.3555 | 4606744
Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     
Sent from Meadowbank