

**APPENDIX 16 2025 NON REPORTABLE SPILLS**

---

Date and time of occurrence	Contaminant	Estimated quantity	Exact location of incident	Description of incident	Describe immediate corrective actions
Friday, January 03, 2025 4:30:00 AM	Hydraulic oil	20L	E&I Parking	While grading the E&I parking, the employee realized that oil was leaking from his grader. Some snow had build-up and froze around the O-Ring of the hydraulic line, causing it to loosen the O-Ring and creating the spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in Landfarm.
Monday, January 06, 2025 1:30:00 PM	Hydraulic Oil	10L	WRSF3	Hydraulic hose broke on an equipment (Dozer) on the Waste Rock Storage Facility 3 resulting in a 30 L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in the Landfarm.
Monday, January 13, 2025 3:00:00 AM	Engine coolant	20L	TIRI01	While a haul truck descended the ramp into the pit, a coolant hose ruptured resulting in a 20L of coolant spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a drum.
Monday, January 13, 2025 7:00:00 AM	Hydraulic Oil	20L	Dyno plant laydown	A worker noticed a 20L spill of hydraulic oil under a machine.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Friday, January 17, 2025 10:30:00 AM	Engine coolant	10L	TIRI01	While a haul truck descended the ramp into the pit, a coolant hose ruptured resulting in a 20L of coolant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in drum.
Saturday, January 18, 2025 4:00:00 AM	Engine coolant	5L	TIRI01	A worker noticed a leak coming from the haul truck auxiliary heating system resulting in a 5L engine coolant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in drum.
Sunday, January 19, 2025 6:30:00 PM	Engine coolant	10L	Pump pit	As a driller began to move the drill, he realized that coolant was leaking from the drill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in drum.

Tuesday, January 21, 2025 4:00:00 PM	Diesel		3 Million Fuel Farm	As an operator was fueling equipment, the nozzle got stuck and didn't turn off. All the spilled fuel was caught in the drip pan.	Cleaned the drip pan with spill pads and placed the spill pads in the appropriate bin.
Wednesday, January 22, 2025 3:00:00 AM	Hydraulic oil	15L	TIRI01	When starting the hydraulic system warmup of the drill, the operator smelled burnt oil. Upon inspection, a 15L hydraulic oil leak was discovered.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Friday, January 24, 2025 1:00:00 PM	Hydraulic oil	25L	Crane pad	While extending the boom on crane, the boom hydraulic hose failed resulting in a 25L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Saturday, January 25, 2025 6:30:00 AM	Engine oil	50L	WRSF3	While warming up the hydraulic system of the excavator, the operator noticed the equipment was not responding as usual. Upon investigation, it was discovered that one flange for the hose was missing 3 out of 4 bolts.	Contaminated material was scrapped and disposed of at the snow cell.
Sunday, January 26, 2025 3:30:00 AM	Hydraulic oil	20L	TIRI01	The bolt holding the flange connection on an excavator has come loose, causing the O-ring to break and the hydraulic oil to leak.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Tuesday, January 28, 2025 5:30:00 AM	Hydraulic oil	4L	E&I operation parking west side msb	An hydraulic hose broke on a loader, resulting in a 4L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Wednesday, January 29, 2025 3:00:00 AM	Hydraulic oil	20L	OP2	The push plate cylinder broke on the haul truck, spilling 20 liters of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, January 29, 2025 10:00:00 AM	Coolant	0.5L	KCG Laydown	A worker observed a coolant spill from a leak on a parked tractor truck. The extreme cold allowed the fitting to contract, resulting in a very slow leak.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and

					disposed of in quatrex bag.
Wednesday, January 29, 2025 11:10:00 PM	Hydraulic Oil	1L	KCG Laydown	A leaking hydraulic fitting was discovered on a haul truck.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, February 02, 2025 11:00:00 PM	Coolant	2L	KCG Parking Lot	A worker observed a spill on the ground when walking in the parking area. Following investigation, it was found the water truck had been parked there, and the water pump for the radiator failed, resulting in a spill of coolant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Friday, February 07, 2025 2:45:00 AM	Hydraulic oil	6L	WRSF6	The operators had left the power take off (PTO) running. The failure of a pressure relief valve allowed pressure to build up within the system, causing the weakest component (the O-ring) to fail, resulting in a 6 L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in the Landfarm.
Friday, February 07, 2025 4:00:00 AM	Motor Oil	5L	Dyno plant	Portable air compressor running outside of dyno had a 5 L motor oil leak during start up.	Contaminated material was scrapped and disposed of in the dyno plant sump.
Monday, February 10, 2025 7:30:00 AM	Emulsion	2L	Emulsion loading area-portal 1	Empty Emulsion bin valve stayed open and caused a spill at the emulsion loading area at portal 1, which is a lined area.	Emulsion was scrapped and put back in the emulsion plant.
Wednesday, February 12, 2025 7:30:00 AM	Engine coolant	1L	TIRI01	A driller noticed coolant dripping from the drill. The coolant hose was rubbing on a steel part of the drill and eventually wore out.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Wednesday, February 12, 2025 1:30:00 PM	Diesel	2L	TIRI01	An employee noticed a spill under the pickup truck. The fuel line valve was slightly open resulting in a diesel spill of 2L.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, February 12, 2025 3:00:00 PM	Hydraulic oil	20L	Drill location 300-144	An hydraulic hose of a drill ruptured resulting in a 20L of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, February 16, 2025 2:30:00 PM	Hydraulic oil	94L	Pump01 pit	The operator of the haul truck drove over a boulder which damaged a hydraulic oil hose located	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material

				under the truck, resulting in a 94L hydraulic oil spill.	was scrapped and disposed of in the Landfarm.
Monday, February 17, 2025 12:00:00 AM	Engine coolant	47L	Pump01 pit	Haul truck operator called the excavator operator to advise that something was leaking from behind the excavator. Operator shut off the engine right away to go look. Upon investigation, a hydraulic hose broke resulting in a 47L spill.	A secondary containment was placed under the spill. Contaminated material was scrapped and disposed of in a hazmat bin. Large boulders were placed in WRSF6.
Tuesday, February 18, 2025 4:30:00 PM	Hydraulic oil	3L	Dion dome parking lot	An E&I supervisor reported a spill under a parked telehandler at the Dion Dome. Upon investigation, no mechanical problem was found. It probably leaked after being dropped off at the Dion dome.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Thursday, February 20, 2025 7:30:00 PM	Hydraulic oil	26L	WRSF6	A bulldozer operator was pushing a load at the WRSF6 when he noticed the equipment was spilling. The flange bolt has broken, causing the hose O-ring to rupture and spilling 26L of Hydraulic oil	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was temporarily placed in WRSF6, identified with candles, and will be moved to the Landfarm.
Friday, February 21, 2025 4:30:00 PM	Engine coolant	36L	TIRI01	Auxiliary heating system hose broke on an excavator resulting on a coolant spill.	Spill occurred on the Ore pad. Ore will be processed at the Process plant.
Saturday, February 22, 2025 7:00:00 AM	Engine coolant	84L	Pump01 pit	A coolant hose broke on an excavator resulting on an 84L spill.	A secondary containment was placed under the spill. Remaining contaminated material was placed in WRSF6 as per the Spill Contingency Plan.
Sunday, February 23, 2025 11:00:00 PM	Diesel fuel	75L	Core shack	When the fuel truck was parked, operators saw fuel coming out of the vent/overflow..	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin
Monday, February 24, 2025 4:30:00 PM	Coolant	2L	East side of process plant parking	A water pump failure caused a 2L coolant leak from a pick-up onto the ground while parked on the east side of the process plant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin
Thursday, February 27, 2025 7:00:00 AM	Power steering fluid	1L	MSB parking lot	While conducting pre-op of a pick-up, operation noticed reservoir of power steering fluid was empty and the presence of	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material

				power steering fluid on the ground. Cold temperature was identified as the root cause.	was scrapped and disposed of in a hazmat bin.
Friday, February 28, 2025 12:00:00 AM	Hydraulic oil	30L	OP2 SHG	The operator of a haul truck was not able to dump. The operator got out of his truck and noticed a 30L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and processed at the Process plant.
Friday, February 28, 2025 12:00:00 PM	Fire water	20L	South of ERT stairwell	While thawing out the frozen fire suppression system, there was a sudden release of fire water from the pipe. Some of the water flowed out the door onto the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the snow cell.
Sunday, March 02, 2025 10:30:00 AM	Hydraulic Oil	2L	Tiri01	While working in Tiri 1, a hydraulic hose failed on an excavator, resulting in a 2L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm
Wednesday, March 05, 2025 12:00:00 AM	Coolant	2L	Haul Road	A drill overheated while tramping from the maintenance shop into the pit, resulting in a 2L spill of coolant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Saturday, March 08, 2025 2:45:00 AM	Coolant	84L	PUMP01	A 84L spill of coolant occurred when a heating hose failed on the excavator.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Sunday, March 09, 2025 10:30:00 AM	Coolant (glycol)	1L	WRSF6	A haul truck's radiator cell cracked, causing a pinhole to form in the radiator, resulting in a 1L spill of coolant on WRSF6.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Tuesday, March 11, 2025 1:30:00 PM	Hydraulic Oil	90L	OP2	A hydraulic hose of a haul truck ruptured resulting in a 90L of hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and

					disposed of at Landfarm.
Tuesday, March 11, 2025 8:30:00 PM	Hydraulic Oil	30L	Tiri01	A hydraulic hose of a drill ruptured, resulting in a 30L of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Tuesday, March 25, 2025 10:30:00 AM	Coolant	10L	Maintenance yard	Employee was driving a haul truck to the Maintenance shop for preventive maintenance. Upon parking, they realized that the coolant hose was damaged and spilled on the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Sunday, March 30, 2025 10:00:00 AM	Hydraulic Oil	50L	WRSF6 (Northeast corner)	50 liters of hydraulic oil spilled from a dozer after a bolt failed on the steering block.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, April 02, 2025 5:30:00 PM	Sewage	30L	Wing 16	30 L of sewage spilled onto the industrial pad outside the Wing 16 lift station. Upon inspection, it was discovered the lift station pump impeller was obstructed by non-compliant material, which led to the pump's failure and the lift station to overflow.	Upon discovering the spill, a vacuum truck and a plumber were dispatched to respond to the spill. The vacuum truck was utilized to empty the contents within the secondary containment. The contaminated material was excavated and transported to Landfarm A in accordance with the Spill Contingency Plan.
Thursday, April 03, 2025 11:30:00 AM	Hydraulic oil	75L	E&I Parking	After parking the haul truck, the operator notice a spill under the equipment. After investigation, it was discovered that a hydraulic line failed resulting in a 75L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Sunday, April 06, 2025 1:00:00 AM	Hydraulic oil	55L	Tiri01	While operating the dozer, the operator noticed a wet spot on the ground. Upon inspection, he discovered a hydraulic oil leak caused by a broken bolt on the steering pump. The bolt head had snapped off,	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.

				loosening the clamp and allowing oil to escape from the fitting.	
Thursday, April 10, 2025 3:30:00 AM	Hydraulic oil	60L	Burn pad of WRSF3	During operations in the area, a main hydraulic line on the loader failed, resulting in a spill of 60 litres of hydraulic fluid.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Thursday, April 10, 2025 11:30:00 AM	Engine coolant	40L	TIR01	While operating the excavator, the operator observed steam emitting from the rear of the machine. Investigation revealed that the cooler fan blades had broken, and debris from the failure severed a coolant hose, resulting in a 40L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Saturday, April 12, 2025 11:00:00 PM	Diesel fuel	20L	MSB Shop yard	The underground haul truck was dripping fuel while waiting on the parking lot resulting in a 20L spill.	Contaminated material was scrapped and disposed of in a hazmat bin.
Monday, April 14, 2025 4:00:00 PM	Fuel	30L	6 million fuel farm	While fueling the fuel truck, the worker noticed that the truck was leaking through the overflow and vent tubes.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the contaminated snow cell.
Monday, April 14, 2025 4:00:00 PM	Fuel	30L	6 million fuel farm	While fueling the fuel truck, the worker noticed that the truck was leaking through the overflow and vent tubes.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the contaminated snow cell.
Saturday, April 19, 2025 7:00:00 PM	Engine coolant	53L	Pump02	Operator saw fluid on the ground when he backed up with the excavator. Investigation revealed that a coolant hose broke, resulting in a spill of approximately 40 litres.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped.
Sunday, April 20, 2025 11:00:00 AM	Brake fluid	60L	OP2	While dumping at the crusher station, the haul truck operator heard a loud noise beneath the vehicle. Upon inspection, it was determined that a brake caliper had failed.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.

Sunday, April 27, 2025 10:30:00 AM	Coolant	9L	OP2	Haul truck was hauling to the crusher when a coolant line broke causing a 9L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Monday, April 28, 2025 1:00:00 PM	Hydraulic oil	22L	TIR01	A corroded fitting in the Tower Light Truck's transmission system failed, causing a 22L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Tuesday, April 29, 2025 2:30:00 AM	Hydraulic oil	3L	OP2	A hydraulic line broke on an excavator causing a 3L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, May 07, 2025 2:30:00 AM	Diesel fuel	8L	Church Heavy equipment parking	While refueling a haul truck, the worker experienced a delay in the fast-fill system's response, resulting in a fuel spill before the system shut off.	Contaminated material was scrapped and disposed of at Landfarm.
Friday, May 09, 2025 10:00:00 AM	Hydraulic Oil	2L	West of Ore Silo	A component failure on a crane parked on the pad resulted in a 2L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Friday, May 09, 2025 10:00:00 PM	Hydraulic Oil	80L	Km 11 Bridge	While clearing snow with an excavator near the bridge at km 11 in preparation for waterline work, a hydraulic hose failed, resulting in an 80L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Friday, May 09, 2025 10:30:00 PM	Hydraulic Oil	10L	Km 4 pad	While clearing snow with a loader at KM4, a hydraulic hose failed, resulting in an 10L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Saturday, May 10, 2025 5:30:00 PM	Hydraulic Oil	15L	Process Plant	A hydraulic hose on the crusher located outside the Process Plant failed, resulting in an 15L hydraulic oil spill	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and

					disposed of at Landfarm.
Monday, May 12, 2025 4:30:00 AM	Coolant	20L	OP-2	A coolant hose on a loader failed resulting in a 20L spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Tuesday, May 13, 2025 1:00:00 PM	Hydraulic oil	1L	MSB parking lot	Approximately 1L of hydraulic oil was found on the ground in the MSB west parking lot by the Environment team, originating from unidentified parked equipment overnight.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, May 14, 2025 3:00:00 PM	Diesel fuel	1L	MSB Parking Lot	A hydraulic spill of 1L was observed beneath a Toyota underground pickup, which was parked in the MSB parking lot.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Thursday, May 15, 2025 3:00:00 PM	Hydraulic oil	6L	TSF	Worker was installing the light tower truck at the TSF. As he activated the lowering of an outrigger, oil started leaking from a hose.	Worker shut down the equipment and used the spill kit.
Thursday, May 15, 2025 10:00:00 PM	Hydraulic oil	4L	Rondelle Pad Awar	Operator was back blading with a loader, when the quick attach fitting for the hose failed.	Equipment was stopped, spill kit was used to contain product, called supervisor for fitting replacement.
Monday, May 19, 2025 6:30:00 AM	Transmission Oil	2L	TIRI01	A frozen chunk of mud detached from the undercarriage of the mine helper pickup, damaging two transmission hoses in the open pit.	Contaminated material will be processed at the Process Plant.
Tuesday, May 20, 2025 8:00:00 AM	Hydraulic oil	15L	Itivia	A hydraulic hose ruptured during startup of the bulldozer, resulting in a spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Tuesday, May 20, 2025 5:00:00 PM	Hydraulic oil	20L	AWAR KM12	While traveling along the AWAR, the driver noticed an oil leak coming from the semi-truck.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, May 21, 2025 2:00:00 PM	Hydraulic Oil	30L	TIRI01	A rupture in the rear hydraulic brake hose of haul truck caused a spill of approximately 30 liters of hydraulic oil.	Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, May 21, 2025 10:49:00 PM	Hydraulic Oil	55L	KCG Parking Ditch	Following brake line repairs, haul truck was relocated from the Tiri 1 open pit to the KCG parking area. Upon	Contaminated material was scrapped and disposed of at Landfarm.

				exiting the vehicle, the operator noticed a rupture in the hoist cylinder hose.	
Friday, May 23, 2025 2:00:00 PM	hydraulic oil	2L	Inukshuk Laydown	A loose fitting on the hydraulic hose of an excavator caused a spill of approximately 2 liters of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Wednesday, May 28, 2025 9:30:00 AM	Hydraulic Oil	5L	Pump01	While placing material on the Pump 1 slope (thermal cap), the haul truck operator noticed hydraulic oil droplets on the ground.	Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, May 28, 2025 10:00:00 PM	Hydraulic Oil	50L	TIRI01	An unidentified ground impact caused partial detachment of the skid plate's supporting frame on haul truck. The displaced frame damaged transmission components and hoses, resulting in a hydraulic fluid spill of approximately 50 liters	Contaminated material was scrapped and will be processed at the Mill.
Sunday, June 01, 2025 10:30:00 PM	Copper sulfate	2L	Mill Reagent Pad	While retrieving copper sulphate bags from the sea container to transport them into the mill, an employee experienced a minor spill. One of the bags tipped over on the Manitou fork rack and broke open, causing a small amount of copper sulphate to spill at the front of the container. The employee promptly secured the broken bag inside a quatrex bag for safe transport into the mill. During the process, some copper sulphate spilled onto the pallet and a small amount was lost along the way.	Contaminated material was scrapped and disposed in the Process Plant.
Monday, June 02, 2025 7:00:00 AM	Hydraulic oil	40L	Warehouse Pad 1	While positioning a container on the second level, a hydraulic hose at the rear of the boom ruptured, causing a 40L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Monday, June 02,	Diesel fuel	10L	Itivia fuel farm	After filling the fuel totes, a worker observed a wet	Spill pads were deployed to clean up

2025 1:30:00 PM				area near the storage container. Upon opening the container, they discovered that the bottom cap on one of the totes was not fully secured causing a 10L diesel fuel spill.	the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Thursday, June 05, 2025 3:30:00 AM	Coolant	50L	OP2 extention	While performing routine tasks at the OP2 extension, the operator identified a coolant line failure on the loader causing a 50L coolant spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Saturday, June 14, 2025 7:00:00 AM	Glycol	30L	Crusher pad	During crusher repairs, approximately 30L of glycol spilled from an HVAC pipe due to a faulty valve.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin.
Sunday, June 15, 2025 4:00:00 AM	Hydraulic oil	5L	TIR01	The operator observed oil drips on the ground and traced the source to a damaged hose on a haul truck.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, June 15, 2025 11:30:00 AM	Hydraulic oil	1L	MSB parking lot	1L of hydraulic oil spill discovered at the MSB parking lot during a site tour.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, June 29, 2025 9:00:00 AM	Hydraulic oil	50L	Warehouse Pad 1	A tote of oil tipped over inside a shipping container. While attempting to reposition it, the operator caught the tote on an internal locking mechanism, puncturing it and causing a 50L hydraulic oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Tuesday, July 01, 2025 9:00:00 AM	Hydraulic oil	5L	HDD Pad in Itivia	While positioning a drill, drills got it hung up on the rockface causing it to go unbalanced and spill 5L of hydraulic oil on the surrounding area.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, July 02, 2025 1:30:00 PM	Diesel fuel	10L	KCG Parking lot	Fuel nozzle failed to disengage upon loader's tank fill-up, resulting in approximately 10L of fuel being sprayed onto the ground	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.

Wednesday, July 02, 2025 8:30:00 PM	Hydraulic oil	8L	CP2 ramp	Worker parked the water truck prior to refilling. Upon return, oil was observed leaking from the sight glass.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Friday, July 04, 2025 1:30:00 PM	Hydraulic fluid	20L	OP2	While dumping at surface, the haul truck experienced a hydraulic hose or fitting failure, releasing fluid onto the ground at OP2.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Saturday, July 05, 2025 8:00:00 PM	Coolant	20L	OP-2 near the OPLG pile	An elbow fitting in a loader failed, resulting in a 20L spill of coolant.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Friday, July 11, 2025 2:00:00 AM	Hydraulic oil	30L	OP2 Waste pad	A hydraulic hose failed on a haul truck resulting in a 30L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Sunday, July 13, 2025 4:30:00 PM	Engine coolant	5L	WesMeg haul road	A coolant hose failed on an excavator, resulting in a 5L spill of coolant	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Wednesday, July 16, 2025 3:30:00 PM	Hydraulic oil	10L	Surface Fuel Farm OP2	While approaching OP2 for refueling, the operator exited the haul truck and observed a minor hydraulic leak	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Monday, July 21, 2025 4:00:00 PM	Engine Oil	3L	Awar Near km 8	Engine failed on a pickup, resulting in a 50L spill of engine oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Monday, July 28, 2025 1:30:00 AM	Hydraulic oil	40L	Tiri 1 10010MS31	A hydraulic hose failed on a haul truck resulting in a 40L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Monday, July 28,	Hydraulic oil	30L	AWAR - Kilometer 20	A hydraulic hose failed on a loader resulting in	Spill pads were deployed to clean up

2025 7:30:00 AM				a 30L spill of hydraulic oil.	the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Saturday, August 02, 2025 6:30:00 AM	Diesel	5L	3 Million Fuel Farm	While refueling the telehandler, the small nozzle failed to shut off automatically, causing the tank to overflow.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, August 03, 2025 6:30:00 AM	Hydraulic Oil	5L	MSB parking lot	An oil leak was identified on a pickup truck at the start of the shift.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, August 03, 2025 4:00:00 PM	Diesel Fuel	60L	TIRI01	While preparing to refuel an excavator, the fuel truck operator activated the PTO to engage the pump. This caused a leak at the butterfly valve on the fill line, attributed to a deteriorated o-ring that failed under pressure.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, August 10, 2025 10:30:00 AM	Hydraulic Oil	5L	North of Process Plant laydown	A 5L hydraulic oil spill was found beneath pallets in the Process Plant north yard following Sunday's cleanup.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in the Process Plant.
Thursday, August 14, 2025 3:30:00 PM	Hydraulic oil	20L	KM 6 Inukshuk Quarry	While operating an excavator, the worker observed an oil leak from underneath the equipment, resulting in a 20L spill on the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Friday, August 15, 2025 8:00:00 AM	Motor oil	2L	Km 4 - Bypass Rd.	A minor oil leak was identified during inspection of excavator.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Monday, August 18, 2025 2:00:00 AM	Hydraulic Oil	75L	Meliadine - Tiri 01 - Ramp - 10020 Level	A haul truck struck a rock that had fallen from another truck's box onto the roadway, damaging its hydraulic system and causing a spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Monday, August 18,	Diesel fuel	60L	3 Million Fuel Farm	During refueling, an underground G Scoop	Spill pads were deployed to clean up

2025 1:00:00 PM				overfilled its tank, resulting in a 60L fuel spill..	the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Monday, August 18, 2025 2:30:00 PM	hydraulic oil	2L	Welding Shop	While operating a manlift, the employee observed hydraulic oil leaking from the manifold.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Monday, August 18, 2025 3:30:00 PM	Coolant	4L	TIRI01	While preparing a pad for the production excavator, the operator of a excavator noticed coolant pooled beneath the machine. Upon inspection, coolant was found slowly dripping from the rear, caused by a worn hose on the DPF system.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of accordingly.
Wednesday, August 20, 2025 8:00:00 AM	Hydraulic Oil	80L	TIRI01	While being loaded by a excavator, a haul truck was observed leaking oil. The excavator operator contacted the truck operator to dump the load for safe access, but the box failed to lift. The excavator operator then emptied the truck box to secure the equipment for inspection.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in the Process Plant.
Friday, August 22, 2025 4:00:00 PM	Hydraulic Oil	10L	Paste Plant Pad	While grading the Past Plan pad, the operator struck a rock, resulting in a broken hose fitting.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Saturday, August 23, 2025 3:00:00 PM	Hydraulic oil	50L	Rankin Inlet Bypass Road KM3	While positioning the HDPE water line for backfill near AWAR, the excavator experienced a hydraulic hose failure in the track head.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Thursday, September 04, 2025 6:30:00 AM	Diesel fuel	10L	KCG parking	CAT 980M Loader	During a routine walkaround inspection, the operator noticed a wet spot beneath the equipment. Upon

					notifying their supervisor, it was determined that the spill originated from the breather during refueling.
Sunday, September 14, 2025 10:30:00 AM	Diesel fuel	11L	3 Million Fuel Farm	scoop and wiggins	While refueling the scoop, the small nozzle failed to shut off automatically, causing the tank to overflow.
Sunday, September 14, 2025 3:30:00 PM	Hydraulic oil	2L	Apache Pass	Excavator HB -365 # 23-0304	While operating the excavator, the worker observed oil leaking from the top of the main boom. Inspection revealed a worn O-ring in the hose.
Wednesday, September 24, 2025 6:30:00 AM	Hydraulic oil	60L	Portal 3	Scoop 6	While mucking a blast, the operator was preparing to dump material onto the Portal 3 waste pad when a hydraulic hose on the lift cylinder failed.
Saturday, September 27, 2025 12:30:00 AM	Engine coolant	10L	TIRI-01	Haul truck HD605	A coolant hose ruptured on the haul truck, resulting in a 10L engine coolant spill.
Monday, September 29, 2025 10:30:00 PM	Engine Oil	30L	CP2	Haul Truck CAT775G	Following an operational error, a haul truck rolled onto its side, resulting in a 30L engine oil leak through the breather.
Friday, October 03, 2025 2:00:00 PM	Engine oil and coolant	50L	WRSF1 Ramp	A loaded haul truck experienced a sudden engine failure while ascending WRSF1. A piston rod punctured the engine block, causing an estimated 50 L engine oil spill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Tuesday, October 07, 2025 1:00:00 AM	Diesel Fuel	350L	3 Million Fuel Farm	During truck refueling, a malfunction in the Scully system failed to stop fuel flow, resulting in overfilling and a spill from the tank overflow into secondary containment.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Tuesday, October 07, 2025 3:30:00 PM	Jet A Fuel	87L	Explo Helipad	During helicopter refueling, Jet-A fuel overflowed from the top of a 25-k tank due to the valve between the two Jet-A tanks not being closed.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the

					Landfarm. Remediation is still ongoing.
Friday, October 10, 2025 2:30:00 PM	Hydraulic oil	3L	Rondell Pad km 4	Hydraulic hose failure occurred as the telehandler was preparing to move material.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Tuesday, October 14, 2025 12:00:00 PM	hydraulic oil	10L	TIRI01	While completing mucking in Portal 3, the scoop operator exited the area and dumped the bucket at the muck pile. The partner then alerted the operator to an oil leak on the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Wednesday, October 15, 2025 3:00:00 AM	Hydraulic Oil	60L	TIRI01	While traveling with the loader, a rear differential component failed, causing an estimated 60 L hydraulic oil spill	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Wednesday, October 15, 2025 6:05:00 AM	Engine Oil	3L	Pump	Approximately 3L of engine oil spilled due to an improperly secured oil cap on a drill.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Wednesday, October 15, 2025 10:30:00 AM	Engine Oil	2L	MSB Core shack Drop zone	Approximately 20L of engine oil spilled due to a mechanical issue on a tractor.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Monday, October 20, 2025 3:00:00 PM	Anti-freeze	1L	Portal 3	After winterizing the bolter with antifreeze, coolant overflowed upon restart due to excessive antifreeze added during the process.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, October 22, 2025 11:30:00 PM	Diesel Fuel	10L	Portal 3 laydown	An open-pit fuel man was refueling an underground scoop when fuel leaked past the tank cap while using the fast-fill nozzle.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.

Sunday, October 26, 2025 1:00:00 PM	Diesel	6L	6 Million Fuel Farm	While beginning to refuel a pickup, the nozzle detached from the hose.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in a hazmat bin
Friday, October 31, 2025 6:30:00 AM	Hydraulic Oil	2L	AWAR Km8.8	A 2L spill of hydraulic spill from unknown equipment was discovered by Construction at KM8.8.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Sunday, November 02, 2025 10:00:00 PM	Hydraulic oil	15L	Burn Pad	While emptying roll-off bins at the burn pad, a hydraulic line on the boom disconnected, causing a spill of approximately 15 liters of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Wednesday, November 05, 2025 3:00:00 PM	Diesel fuel	40L	East Vent Raise	When the East vent raise was started, a fuel pump regulator was set too high, resulting in a spill of approximately 40 liters of diesel.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Wednesday, November 05, 2025 3:00:00 PM	Glycol	25L	East Vent Raise	When the vent raise was started, the glycol return line leaked causing a spill of 25L of glycol.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Thursday, November 06, 2025 8:30:00 AM	Hydraulic oil	0.5L	Core Shack Dome	Hamlet water truck leaked from PTO causing a spill of 0.5L of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Saturday, November 08, 2025 4:30:00 PM	Hydraulic oil	0.2L	Warehouse Pad1	While placing a barrel of hydraulic oil on a skid, the fork struck the barrell, puncturing a small hole in its side. Approximately 200 ml of oil leaked inside the C-can.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Friday, November 14, 2025 11:00:00 AM	Transmission fluid	1L	KCG Parking	Approximately 1 liter of transmission fluid leaked at the truck's parking location due to a transmission failure	Contaminated material (snow) was scrapped and disposed of in the contaminated snow cell.
Saturday, November 15, 2025 11:30:00 PM	Coolant	20L	TIRI01	While driving an excavator up the TIRI01 ramp, the operator realized that the radiator was damaged and leaking on the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in quatrex bag.

Tuesday, November 18, 2025 7:00:00 AM	Transmission fluid	5L	Haul Road	After the haul truck displayed a low transmission fluid code, the operator stopped to inspect and discovered approximately 5 liters had leaked onto the ground	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Saturday, November 29, 2025 5:30:00 PM	Engine Oil	3L	Portal Muck Pad	A mechanic observed a small oil puddle beneath the boom truck engine. Inspection indicated the engine oil breather likely froze, causing oil to exit through the dipstick.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of in quatrix bag.
Sunday, November 30, 2025 12:30:00 AM	Hydraulic oil	22L	TIRI01	While pushing material at the bottom of TIRI01, the loader operator noticed oil on the ground while backing up. Investigation revealed a broken hydraulic hose.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Landfarm.
Tuesday, December 02, 2025 2:00:00 AM	Diesel	60L	Portal 3	At Portal 3, the fuelman began refueling the scoop using fast fuel and then proceeded to refill the DEF on the opposite side of the equipment. During the process, he observed fuel on the ground and, upon inspection, identified that the fuel was discharging from the scoop's vent.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Wednesday, December 03, 2025 9:00:00 AM	Hydraulic Oil	1L	Portal 3	The engine oil breather froze two days prior the incident and was replaced. It appears the breather may have frozen again, or the machine may not have been fully thawed by the frost fighter, resulting in a 1L spill of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin.
Thursday, December 04, 2025 12:00:00 AM	Glycol	60L	East Vent Raise	The employee observed pooling beneath the Vent Raise control room, which appeared to be an old spill. Upon investigation, it was determined that the spill originated from Burner 12 heat exchanger valves and gaskets, leaking through gaps in the floor	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Contaminated Snow cell.

Friday, December 05, 2025 1:45:00 AM	Hydraulic Oil	10L	TIRI01	A hydraulic hose on an haul truck driving in TIRI01 ruptured, likely due to extreme cold. A nearby operator noticed the leak and notified the truck operator.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Saturday, December 06, 2025 12:00:00 PM	Coolant	5L	TIRI01	While draining a drill's water tank at TIRI01, a corroded heating element inside the tank ruptured, causing approximately 5 liters of coolant to spill onto the ground.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Contaminated Snow cell.
Saturday, December 06, 2025 3:30:00 PM	Diesel fuel	30L	Gatehouse Generator	An injector return hose split and detached from its fitting, causing fuel to spill into the generator's spill pan. The pan overflowed, resulting in approximately 30 liters of fuel spilling onto the seacan floor and out the door at the gatehouse.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at the Contaminated Snow cell.
Wednesday, December 10, 2025 1:20:00 AM	Hydraulic Oil	65L	TIRI01	Approximately 65 liters of hydraulic oil spilled from a failed hose on a haul truck. While ascending the Tiri 1 ramp with a load, the operator observed a low-level warning on the dashboard and informed their supervisor. At the top of the ramp, a high-level warning appeared, prompting the operator to stop the truck. A drip trail approximately 860 meters long was identified.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Tuesday, December 16, 2025 11:00:00 AM	Diesel	25L	6 Million Fuel Farm	While refueling a haul truck at the Fuel Farm, the operator went inside the station, assuming the pump would shut off automatically. Upon looking outside, he noticed fuel overflowing from the vent near the truck's fuel cap.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Thursday, December 18, 2025 8:00:00 AM	Hydraulic Oil	10L	Pump 2 Automation Pad	The oil cap was dislodged due to engine back pressure, resulting in a spill of approximately 10	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material

				liters of hydraulic oil on the Automation Pad	was scrapped and disposed of at Landfarm.
Friday, December 19, 2025 1:00:00 AM	Diesel	19.23L	Portal 3	While refueling a scoop at Portal 3, the nozzle failed to shut off properly and continued to flow slowly due to cold weather, resulting in a diesel spill of approximately 19.23 liters.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Friday, December 19, 2025 1:30:00 AM	Hydraulic Oil	5L	KCG Yard Parking	While fueling a haul truck, the operator noticed a minor leak from the PTO. The PTO piston seal failed, resulting in a spill of approximately 5 liters of hydraulic oil at the KCG Parking.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Friday, December 26, 2025 9:30:00 AM	Hydraulic Oil	2L	Paste Plant	An unreported collision with a manlift damaged the hydraulic oil tank in the Paste Plant yard, resulting in a spill of approximately 2 liters of hydraulic oil. The incident was discovered by the Environment team during an inspection.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.
Saturday, December 27, 2025 4:00:00 PM	Hydraulic Oil	20L	WRSF6	A dozer became stuck on a boulder while changing direction on WRSF6, causing damage to the torque converter and resulting in a spill of approximately 20 liters of hydraulic oil.	Spill pads were deployed to clean up the spill and disposed of in the appropriate bin. Contaminated material was scrapped and disposed of at Landfarm.