



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 05-08-2023	REPORT TIME 11:20	<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT		REPORT NUMBER _____
B	OCCURRENCE DATE: MONTH – DAY – YEAR 05-07-2023	OCCURRENCE TIME 14:00			
C	LAND USE PERMIT NUMBER (IF APPLICABLE) KVPL11D01	WATER LICENCE NUMBER (IF APPLICABLE) 2AM-MEL1631			
D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Meliadine Gold Project		REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN		
E	LATITUDE DEGREES 63 MINUTES 2 SECONDS 21		LONGITUDE DEGREES 92 MINUTES 13 SECONDS 41		
F	RESPONSIBLE PARTY OR VESSEL NAME Agnico Eagle Mines Ltd.	RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Meliadine, Rankin Inlet, Nunavut, X0C 0G0			
G	ANY CONTRACTOR INVOLVED N/A	CONTRACTOR ADDRESS OR OFFICE LOCATION N/A			
H	PRODUCT SPILLED Suspended Solids	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES To be determined	U.N. NUMBER N/A		
	SECOND PRODUCT SPILLED (IF APPLICABLE) N/A	QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES N/A	U.N. NUMBER N/A		
I	SPILL SOURCE Snow melt containing sediment	SPILL CAUSE Freshet	AREA OF CONTAMINATION IN SQUARE METRES Unknown		
J	FACTORS AFFECTING SPILL OR RECOVERY None	DESCRIBE ANY ASSISTANCE REQUIRED None	HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT None		
K	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS While conducting a routine inspection, runoff was observed flowing through the water management structures at monitoring station MEL-SR-1 at Itivia. Turbidity field readings show results indicative that TSS concentrations could exceed the NWB Water License 2AM-MEL1631 criteria for TSS. Sediment and erosion controls were deployed to mitigate the transport of sediment. This report is submitted as due diligence, as the water sample results from the laboratory have not yet been received. Location of spill: 62 47'59.85"N, 92 5'35.63"W. The closest water body (Melvin Bay) is approximately 75 m south. Pursuant to Part H, Section 8c of the Water License, a follow-up report will be issued after a closer investigation is completed.				
L	REPORTED TO SPILL LINE BY Randy Schwandt	POSITION Env. Coordinator	EMPLOYER AEM	LOCATION CALLING FROM Meliadine	TELEPHONE 819-759-3555
M	ANY ALTERNATE CONTACT Kyle Conway	POSITION General supervisor	EMPLOYER AEM	ALTERNATE CONTACT Meliadine LOCATION	ALTERNATE TELEPHONE 819-860-1033
REPORT LINE USE ONLY					
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS	
LEAD AGENCY					
FIRST SUPPORT AGENCY					
SECOND SUPPORT AGENCY					
THIRD SUPPORT AGENCY					