



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee	Licensee Representative
Agnico Eagle Mines LTD.	Samuel Tapp
Licence No. / Expiry	Representative's Title
2AM-WTP1830/March 27, 2030	Environment Coordinator
Land Authorization No.	Land Authorization No.
66H/08-01 Quarries	66H/08-02 Haul Road
Date of Inspection	Inspector
September 13, 2022	WRO K AMSEL
Activities Inspected	
<input checked="" type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input checked="" type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:
<input checked="" type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage
<input type="checkbox"/> Other:	

SECTION 1 ☒ **Comments (s. __)** ☐ **Non-Compliance with Act or Licence (s. __)** ☐ **Action Required (s. __)**

On September 13, 2022 Water Resources Officer Kyle Amsel (Inspector) of Crown-Indigenous Relations and Northern Affairs Canada, (CIRNAC) conducted an inspection of Water Licence 2AM-WTP1830 (Licence). The Licence is issued to Agnico Eagle Mines Limited (Licensee) for the use of Waters and deposit of Wastes in support of a Mining Undertaking (Undertaking).

Accompanying the Inspector was Environment Coordinator Samuel Tapp. The aforementioned is here on referred to as Representative.

Preliminary Information

The primary focus of this inspection was completing closures of spills reported to the NT-NU 24hr Spill Reporting Line.

Observations

1. The following spills were inspected and recommended for closure-remediated:

- 2022-396
- 2022-282
- 2022-185
- 2022-085
- 2022-059
- 2022-058
- 2022-009
- 2022-006
- 2021-317
- 2021-128
- 2021-050
- 2021-045
- 2021-008
- 2021-003
- 2020-420
- 2020-328
- 2020-325
- 2020-178
- 2020-140
- 2020-064
- 2020-020
- 2020-019
- 2019-493
- 2019-490
- 2019-442



- 2019-439
- 2. 2020-152 has been inspected though not closed, further remediation is required. Fuel is detected in a 1m² area.
- 3. The following spills occurred inside the pit and are recommended for closure-remediated:
 - 2022-186
 - 2022-158
 - 2022-137
 - 2022-088
 - 2022-066
 - 2021-453
 - 2021-393
 - 2021-296
 - 2021-212
 - 2021-094
 - 2021-013
 - 2020-447
 - 2020-445
 - 2020-422
 - 2020-391
 - 2020-148
 - 2020-143
 - 2020-125
 - 2020-094
 - 2020-093
 - 2020-039
 - 2019-488
 - 2019-474
 - 2019-431


SECTION 2 ☐ Comments (s.____) ☒ Non-Compliance with Act or Licence (s.2) ☐ Action Required (s.____)

No incidents of non-compliance were observed.

SECTION 3 ☐ Comments (s.____) ☐ Non-Compliance with Act or Licence, (s.____) ☒ Action Required (s.3)

Further Actions Required:

- Provide follow up to the Inspector for spill 2020-152

Licensee or Representative	Inspector's Name
Samuel Tapp	WRO K AMSEL
Signature	Signature 
Date	Date
September 13, 2022	September 13, 2022

Office Use Only: Follow-up report to be issued by Inspector ☐ Yes ☒ No