



Canada

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 10-30-2019		REPORT TIME 13:00		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER _____
	B	OCCURRENCE DATE: MONTH – DAY – YEAR 10-28-2019		OCCURRENCE TIME 11:30		
C		LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) NWB-2AM-WTP1826	
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Whale Tail Project			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 65 MINUTES 01 SECONDS 51			LONGITUDE DEGREES 96 MINUTES 09 SECONDS 21	
	F	RESPONSIBLE PARTY OR VESSEL NAME AGNICO EAGLE MINES LTD		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION BAKER LAKE X0C 0A0		
G		ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
	H	PRODUCT SPILLED Turbidity/Suspended Solids		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES TBD		U.N. NUMBER N/A
I		SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER
	J	SPILL SOURCE Dewatering water (ST-MDMER-5)		SPILL CAUSE Effluent Discharge		AREA OF CONTAMINATION IN SQUARE METRES N/A
K		FACTORS AFFECTING SPILL OR RECOVERY		DESCRIBE ANY ASSISTANCE REQUIRED		HAZARDS TO PERSONS, PROPERTY OR EQUIPMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS				
M		<p>A first water sample was taken at 6:50 on the morning of the 28th, turbidity was then assessed to be at 15,94 NTU and parameters sampled included TSS directed at our external laboratory. As part of our regular water quality sampling, another turbidity reading was taken at 11:30 on the same morning. This reading was noted at 80,10 NTU, exceeding the Water Licence criteria (Part D, Item 7) of 30 NTU. With increasing wind and blizzard conditions on site it was determined to be unsafe to take additional sampling by our personnel or proceed to further actions on the discharge. When conditions permitted to resample the discharge, on the morning of October 29th, the turbidity reading had significantly decreased to 11,90 NTU. Samples were sent to our external laboratory. Spill location : ST-MDMER-5 65°23'51.3" 96°40'49.0"</p> <p>Contact information : Robin Allard 819-860-1414</p>				
	N	REPORTED TO SPILL LINE BY Robin Allard		POSITION General Supervisor		EMPLOYER Agnico Eagle Mines
LOCATION CALLING FROM MEADOWBANK		TELEPHONE 819-759-3555				
O	ANY ALTERNATE CONTACT Nancy Duquet		POSITION Superintendent		EMPLOYER Agnico Eagle Mines	
	ALTERNATE CONTACT MEADOWBANK		ALTERNATE TELEPHONE 819-856-4385			
REPORT LINE USE ONLY						
P	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR		EMPLOYER	
	LOCATION CALLED YELLOWKNIFE, NT		REPORT LINE NUMBER (867) 920-8130			
LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN			FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME		CONTACT TIME		REMARKS
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						