



AGNICO EAGLE

2025-12-23 WTM DIESEL COOLANT HYDRAULIC OIL

GN reference #: 2025-469

Please find the following information as a follow up to the Spill report submitted December 23rd, 2025, by Agnico Eagle Meadowbank division. This detailed report is submitted to the Inspector in compliance with the conditions under the Nunavut Water Board License 2AM-WTP1830, Part H, Item 8c.

Spill Description

During operations along the Whale Tail Haul Road, a snow plow veered off the roadway at approximately km 132. As a result, an estimated 250L Diesel, 5L of Hydraulic Oil, and 5L of Coolant were released onto the ground.



Spill Location: 65°11'28.80 96° 9'43.80

The spill was located along the Whale Tail Haul Road. There were no off-site impacts or discharges. Distance to the closest water body is ~550m to C25-C26 stream

Cause of Spill

Human Error

Remediation Actions

A secondary containment and absorbent pads were placed under the active leaks. After further investigation a total of approximately 250L Diesel, 5L of Hydraulic Oil, and 5L of Coolant spilled from the equipment. Contaminated materials were removed and brought to tailing storage facility at the Meadowbank Complex.



Corrective measures

A health and safety investigation was initiated to identify the root cause of the incident and establish appropriate corrective actions. Furthermore, the incident was reviewed with all drivers to reinforce awareness and prevent recurrence.

Closure

We trust that the above details described appropriately the spill incident that occurred on the Whale Tail Haul Road on December 23rd, 2025, and the cleanup activities. Please contact the undersigned should you have any questions.



Samuel Tapp | Environment Supervisor

samuel.tapp@agnicoeagle.com | Direct 819.759.3555 x4606744 |

Agnico Eagle Mines Limited - Meadowbank Division, Suite 540 - Baker Lake, Nunavut, Canada X0C 0A0

agnicoeagle.com     

Sent from Amaruq