



Canada

RECEIVED

By Manager of Licensing at 4:22 pm, Apr 18, 2011

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH - DAY - YEAR 03-29-2011		REPORT TIME 14:00 hrs		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER 11-087
	B	OCCURRENCE DATE: MONTH - DAY - YEAR 03-21-2011		OCCURRENCE TIME <07:00 hrs		
C		LAND USE PERMIT NUMBER (IF APPLICABLE)		WATER LICENCE NUMBER (IF APPLICABLE) 2BB-BOS0712		
	D	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Aimaoktatuk (Spyder) Lake			REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E		LATITUDE DEGREES 67 MINUTES 39 SECONDS 19		LONGITUDE DEGREES 106 MINUTES 23 SECONDS 34		
	F	RESPONSIBLE PARTY OR VESSEL NAME Hope Bay Mining Ltd.		RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 300, 889 Harbourside Dr. North Vancouver, BC V7P 3S1		
G		ANY CONTRACTOR INVOLVED		CONTRACTOR ADDRESS OR OFFICE LOCATION		
	H	PRODUCT SPILLED Brine (Salt water)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 400 liters		U.N. NUMBER
I		SECOND PRODUCT SPILLED (IF APPLICABLE)		QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER
	J	SPILL SOURCE Diamond Drill Rig		SPILL CAUSE Water Return line failure		AREA OF CONTAMINATION IN SQUARE METRES 25 m2
K		FACTORS AFFECTING SPILL OR RECOVERY Spill is cleaned up		DESCRIBE ANY ASSISTANCE REQUIRED none required		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT
	L	ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The water return line from the drill casing to the brine tank was improperly installed and the returning water spilled on the ice and not in the catchment tank. Approximately 400 liters of brine (calcium chloride and water) (salt water) spilled onto the surface of the ice on Spyder Lake. The salt water and contaminated snow was cleaned up and contained. The surface of the ice was scraped over to remove any residual brine. The return hose and the catchment tank was re-installed properly to prevent a similar occurrence.				
M		REPORTED TO SPILL LINE BY Dave Vokey		POSITION Sr. Env. Coordinator		EMPLOYER Hope Bay Mining
	N	ANY ALTERNATE CONTACT		POSITION		EMPLOYER
O		LOCATION CALLING FROM Hope Bay, NU		TELEPHONE (604)759-4714		ALTERNATE CONTACT LOCATION
	REPORT LINE USE ONLY					
P	RECEIVED AT SPILL LINE BY		POSITION STATION OPERATOR		EMPLOYER	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC		SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED	
Q	AGENCY		CONTACT NAME		CONTACT TIME	
	REMARKS		LEAD AGENCY		FIRST SUPPORT AGENCY	
R	SECOND SUPPORT AGENCY		THIRD SUPPORT AGENCY		REMARKS	
	THIRD SUPPORT AGENCY		REMARKS		REMARKS	