



Canada

RECEIVED

By Manager of Licensing at 4:24 pm, Apr 18, 2011

NT-NU SPILL REPORT

OIL, GASOLINE, CHEMICALS AND OTHER HAZARDOUS MATERIALS

NT-NU 24-HOUR SPILL REPORT LINE

TEL: (867) 920-8130

FAX: (867) 873-6924

EMAIL: spills@gov.nt.ca

REPORT LINE USE ONLY

A	REPORT DATE: MONTH – DAY – YEAR 03-29-2011		REPORT TIME 14:00 hrs		<input checked="" type="checkbox"/> ORIGINAL SPILL REPORT, OR <input type="checkbox"/> UPDATE # _____ TO THE ORIGINAL SPILL REPORT	REPORT NUMBER 11-088
	OCCURRENCE DATE: MONTH – DAY – YEAR 03-26-2011		OCCURRENCE TIME <07:00 hrs			
C	LAND USE PERMIT NUMBER (IF APPLICABLE)			WATER LICENCE NUMBER (IF APPLICABLE) 2BB-BOS0712		
	GEOGRAPHIC PLACE NAME OR DISTANCE AND DIRECTION FROM NAMED LOCATION Aimaoktatuk (Spyder) Lake				REGION <input type="checkbox"/> NWT <input checked="" type="checkbox"/> NUNAVUT <input type="checkbox"/> ADJACENT JURISDICTION OR OCEAN	
E	LATITUDE DEGREES 67 MINUTES 39 SECONDS 19			LONGITUDE DEGREES 106 MINUTES 23 SECONDS 34		
	RESPONSIBLE PARTY OR VESSEL NAME Hope Bay Mining Ltd.			RESPONSIBLE PARTY ADDRESS OR OFFICE LOCATION Suite 300, 889 Harbourside Dr. North Vancouver, BC V7P 3S1		
G	ANY CONTRACTOR INVOLVED			CONTRACTOR ADDRESS OR OFFICE LOCATION		
	PRODUCT SPILLED Brine (Salt water)			QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES 400 liters		U.N. NUMBER
H	SECOND PRODUCT SPILLED (IF APPLICABLE)			QUANTITY IN LITRES, KILOGRAMS OR CUBIC METRES		U.N. NUMBER
	SPILL SOURCE Diamond Drill Rig			SPILL CAUSE Defective Over-pressure Valve		AREA OF CONTAMINATION IN SQUARE METRES 25 m2
J	FACTORS AFFECTING SPILL OR RECOVERY Spill is cleaned up			DESCRIBE ANY ASSISTANCE REQUIRED none required		HAZARDS TO PERSONS, PROPERTY OR ENVIRONMENT
	K ADDITIONAL INFORMATION, COMMENTS, ACTIONS PROPOSED OR TAKEN TO CONTAIN, RECOVER OR DISPOSE OF SPILLED PRODUCT AND CONTAMINATED MATERIALS The over-pressure relief valve on the brine tank malfunctioned causing a spill of approximately 400 liters of brine (calcium chloride and water) (salt water) onto the surface of the ice on Spyder Lake. The salt water and contaminated snow was cleaned up and contained. The surface of the ice was scraped over to remove any residual brine solution. The defective valve has been replaced and drilling has resumed.					
L	REPORTED TO SPILL LINE BY Dave Vokey	POSITION Sr. Env. Coordinator	EMPLOYER Hope Bay Mining	LOCATION CALLING FROM Hope Bay, NU	TELEPHONE (604)759-4714	
	ANY ALTERNATE CONTACT	POSITION	EMPLOYER	ALTERNATE CONTACT LOCATION	ALTERNATE TELEPHONE	
REPORT LINE USE ONLY						
N	RECEIVED AT SPILL LINE BY	POSITION STATION OPERATOR	EMPLOYER	LOCATION CALLED YELLOWKNIFE, NT	REPORT LINE NUMBER (867) 920-8130	
	LEAD AGENCY <input type="checkbox"/> EC <input type="checkbox"/> CCG <input type="checkbox"/> GNWT <input type="checkbox"/> GN <input type="checkbox"/> ILA <input type="checkbox"/> INAC <input type="checkbox"/> NEB <input type="checkbox"/> TC			SIGNIFICANCE <input type="checkbox"/> MINOR <input type="checkbox"/> MAJOR <input type="checkbox"/> UNKNOWN		FILE STATUS <input type="checkbox"/> OPEN <input type="checkbox"/> CLOSED
AGENCY		CONTACT NAME	CONTACT TIME	REMARKS		
LEAD AGENCY						
FIRST SUPPORT AGENCY						
SECOND SUPPORT AGENCY						
THIRD SUPPORT AGENCY						