

Nunavut Regional Office P.O. Box 100 Iqaluit, NU, X0A 0H0

> Your file - Votre référence 2BE-MEA0507 Our file - Notre référence IQA-N 9545-2-2MEAG / 183209

November 20, 2007

Phyllis Beaulieu Licensing Administrator Nunavut Water Board P.O. Box 119 Gjoa Haven, NU, X0A 1J0


Re: Renewal Type "B" Water Licence – 2BE-MEA0507 – Meadowbank Exploration Camp, Meadowbank Project – Agnico-Eagle Mines Ltd.

Indian and Northern Affairs Canada (INAC) has performed a review of the type "B" renewal water license application for Meadowbank Gold Project Exploration Camp, submitted to the Nunavut Water Board (NWB) by Agnico-Eagle Mines Ltd. In conducting our review, INAC has made reference to all the documents on the NWB's FTP-site under 2BE-MEA

## SPILL CONTINGENCY PLAN:

- INAC requests that the Nunavut Spill Report Form be attached in Appendix J of the Spill Contingency Plan. The Nunavut Spill Report Form can be retrieved from the NWB public registry at <a href="http://nunavutwaterboard.org">http://nunavutwaterboard.org</a>.
- Furthermore, INAC requests the Proponent report all spills to both the Nunavut Spill Report Line, Phone: (867) 920-8130, facsimile (867) 873-6924 and Peter Kusugak, INAC Manager of Field Operations, Phone: (867) 975-4295, facsimile (867) 975-4560. Please update table 8.2 in the Spill Contingency Plan to include the aforementioned name and telephone numbers.
- INAC requests that the Proponent updates section 3; *Hazardous Materials Stored on Site*, to list all the hazardous materials and their quantity on site. Currently the list refers to: "Other materials hazardous to the safety of personnel and the environment." This should be clarified further.





## ABANDOMENT AND RESTORATION PLAN

• INAC recommends that all sumps used during the duration of the project be reclaimed in the same manner as suggested in the Abandonment and Restoration Plan under section 4.5, Trenches; namely: "Trenches will be backfilled with the material previously removed and stockpiled beside the trenches. They will be smoothed, re-contoured and fertilized as above."

Should you have any questions or comments, please do not hesitate to contact me at (867) 975-4548 or by email at <a href="mailto:ReinhartF@inac-ainc.gc.ca">ReinhartF@inac-ainc.gc.ca</a>.

Sincerely,

Original Signed By

Froeydis Reinhart Pollution Policy Specialist

