



☒ Original
☐ Follow-Up Report

LAND USE PERMIT INSPECTION FORM

Permittee	Representative
Agnico Eagle Mines Limited	David Frenette
Permit No. / Expiry	Representative's Title
N2013F0030/ April 15 th , 2019	Environmental Coordinator
Other Authorizations	Land / Other Authorizations
2BB-MEA1318	Camp is on IOL
Date of Inspection	Inspector
11/05/2017	WRO Wilson
Activities Inspected	
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage	
<input checked="" type="checkbox"/> Roads/hauling <input type="checkbox"/> :Other <input type="checkbox"/> Other:	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
Section:	Term No.	Condition	Observation No.		
31 (1)(a) Location and Area	1, 3, 4	A	1,2		
31 (1)(b) Time	8	NI	--		
31 (1)(c) Equipment	--	--	3		
31 (1)(d) Methods and Techniques	15	A	4		
31 (1)(e) Type location, capacity and operation of facility	19	A	5		
31 (1)(f) Control or prevent of flooding, erosion, and subsidence of Land	--	NI	--		
31 (1)(g) Use, storage, handling and disposal of chemical or toxic materials	--	A	--		
31 (1)(h) Wildlife and fisheries habitat	--	A	--		
31 (1)(i) Objects and places of recreation, scenic and ecological value	--	--	--		
31 (1)(k) Petroleum fuel storage	--	NI	--		
31 (1)(m) Matters not inconsistent with the regulations	47	A	--		

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<div>1. No concerns in relation to snow cover, or routing.</div> <div>2. No camp, fuel caches or materials were noted along the winter trail route.</div> <div>3. The winter trail was just recently shut down on May 9th, 2017. We did not observe the equipment used during hauling.</div> <div>4. The winter trail appears to utilize frozen water bodies were ever possible.</div> <div>5. The land use area was clean and tidy. The only materials observed were wood stakes used to mark the trail. AEM confirmed that the markers are removed annually.</div>			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Regulations	<input type="checkbox"/> Action Required
No concerns at this time.			
SECTION 3	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Regulations	<input checked="" type="checkbox"/> Action Required
The winter trail construction and operation was done to the satisfactory of the inspector.			
Licensee or Representative		Inspector's Name	
		WRO Wilson	
Signature		Signature	
		Original signed on file	
Date		Date	
		May 11 th , 2017	

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---