

WATER USE INSPECTION REPORT

| | |
|----------------------------------|--|
| Date: August 1,2009 | Licensee Rep. (Name/Title): Martin Eastwood, John Witteman |
| Licensee: Comaplex Minerals Corp | Licence No.: 2BB-MEL0914 (new) |

WATER SUPPLY

| | |
|--|--|
| Source(s): Meliadine Lake | Quantity used: <90 M³ Estimate only. Meter now installed |
| Owner:/Operator: Comaplex Mineral Corp | |

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | | |
|-----------------------|----------------------|----------------------|----------------------|
| Intake Facilities: NA | Storage Structure: A | Treatment Systems: A | Chemical Storage: NI |
| Flow Meas. Device: A | Conveyance Lines: A | Pumping Stations: A | Screen : NI |

Comments: Water is taken from Meliadine Lake for use in Camp. Water is run through filters and UV treatment prior to use in Camp. Water will be re-circulated in the intake line with an on-demand system feeding the camp recorded on newly installed meter. Water use for Drill units will have meters installed by August 21st and used until October 1st to determine baseline usage data for winter/spring usage.

WASTE DISPOSAL

Sewage: Incinerated (Prim./Sec/Ter.): None

| | | | |
|--------------------------|--|--------------|--|
| Natural Water Body: No | Continuous Discharge (land or water): None | | |
| Seasonal Discharge: None | Wetlands Treatment: None | Trench: None | |

Grey water: Discharge to sump. Sump is still requires further work.

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|----------------------------|-------------------------------|----------------|
| Discharge Quality: Unknown | Decant Structure: U | Erosion: None |
| Discharge Meas. Device: NA | Dyke Inspection: NI | Seepages: None |
| Dams, Dykes: NA | Freeboard: NA | Spills: NA |
| Construction: NI | O&M Plan: NA | A&R Plan: NA |
| Discharge: Not metered | Effluent Discharge Rate: None | |

Comments: Human waste is incinerated on site. Grey water is discharged from kitchen and dries to a sump. Initial works undertaken by the licensee to slow the flow of water back to the lake require further efforts. Licensee plans to install a RBC unit pending approval from the NWB.

Solid Waste: Waste is incinerated on site. Ash is transported to Rankin Inlet.

Owner/Operator: Comaplex Minerals Inc.

| | | |
|----------------|---------------------|------------------|
| Landfill: None | Burn & Landfill: NA | Other: (Barrels) |
|----------------|---------------------|------------------|

Comments: Hazardous wastes are consolidated for shipment off site to approved hazardous waste storage area. An approved incinerator is on site. Metal wastes are shipped off site to Rankin Inlet.

FUEL STORAGE: Fuel is stored in double walled metal storage tanks

Waste Oil Storage: Packaged for shipment off site **Owner/Operator:** Comaplex Minerals Corp.

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

| | | |
|------------------------|------------------------------------|-------------------------|
| Berms & Liners: NA | Water within Berms: NA | Evidence of Leaks: None |
| Drainage Pipes: None | Pump Station & Catchments Berm: NA | |
| Pipeline Condition: NI | Condition of Tanks: NI | |

Comments: Secondary containment is sufficient for current fuel stock on site.

SURVEILLANCE NETWORK PROGRAM (SNP)

| | | | |
|--|--------|---|------------|
| Samples Collected : M | | Owner /Operator: Monthly reports (SNP)are provided as required. | |
| 3 | | INAC: Mine sump, Primary containment P1, Camp Sump | |
| Signs Posted | SNP: A | | Warning: A |
| Records & Reporting: records to be provided in annual report | | | |
| Geotechnical Inspection: N/A | | | |

Non-Compliance of Act or Licence: New license issued and effective July 31st, 2009.