

A Report date and time 03/30/97 3:30PM		B Date and time of spill (if known) 03/30/97		C ☒ Original report ☐ Update no. 97-044	
D Location and map coordinates (if known) and direction (if moving) Heliadine Camp (WMC) UTM 541950E 6988850N					
E Party responsible for spill WMC International Ltd Rankin Inlet					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) Diesel (P-50) 450 litres					
G Cause of spill leaks in large bung of several barrels (10 barrels)					
H Is spill terminated? ☒ yes/ ☐ no		I If spill is continuing, give estimated rate no		J Is further spillage possible? ☐ yes/ ☒ no	
K Extent of contaminated area (in square metres if possible) 5m ²				L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) natural depression	
M Containment (natural depression, dykes, etc.) natural depression					
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials All the snow containing diesel near the leaking barrels was shoveled into garbage bags and incinerated in the camp incinerator.					
O Do you require assistance? ☒ no ☐ yes, describe:		P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife None			
Q Comments and/or recommendations Leaking barrels stood upright to prevent leaking from bungs. ** This spill was originally assigned spill # 97-045 in error. It is now assigned 97-044. BELLERIN SPILL LINE, YELLOWKNIFE					
Reported by Alan Sinton		Position, Employer, Location District Geologist - WMC Heliadine		Telephone 819-645-3308	
Reported to C Hendry		Position, Employer, Location Spill line		Telephone 920-8130	