

A Report date and time D'6C'DC 7/97 11:00pm		B Date and time of spill (if known) D'6C'DC May 7/97 11:00am		C Original report D'6C'DC Update no. 92079	
D Location and map coordinates (if known) and direction (if moving) D'6C'DC Meliadine Camp (WMC) UTM 541950E/ 6988850 N					
E Party responsible for spill D'6C'DC Boat Languan - Skidder operator C					
F Product(s) spilled and estimated quantities (provide metric volumes/weights if possible) D'6C'DC Diesel (CP-50) - 100 litres (Jason Grant)					
G Cause of spill D'6C'DC Skidder blade punctured a barrel					
H Is spill terminated? D'6C'DC ☒ yes/d ☐ no/d		I If spill is continuing, give estimated rate D'6C'DC no/d		J Is further spillage possible? D'6C'DC ☐ yes/d ☒ no/d	
K Extent of contaminated area (in square metres if possible) D'6C'DC 2 m ²		L Factors affecting spill or recovery (weather conditions, terrain, snow cover, etc.) D'6C'DC Natural depression			
M Containment (natural depression, dykes, etc.) D'6C'DC Natural depression					
N Action, if any, taken or proposed to contain, recover, clean up or dispose of product(s) and contaminated materials D'6C'DC All the contaminated snow was shovelled into garbage bags and incinerated. The barrel was pumped dry into another barrel.					
O Do you require assistance? D'6C'DC ☐ no/d ☐ yes, describe: D'6C'DC no/d		P Possible hazards to persons, property, or environment; eg: fire, drinking water, fish or wildlife D'6C'DC None			
Q Comments and/or recommendations D'6C'DC Damaged barrel was pumped out and discharged.				FOR SPILL LINE USE ONLY D'6C'DC Lead Agency D'6C'DC DIAND Spill significance D'6C'DC minor Lead Agency contact and time D'6C'DC 05/07/97 22:20 Is this file now closed? D'6C'DC	
Reported by D'6C'DC Alan Sexton		Position, Employer, Location D'6C'DC District Geologist - Meliadine		Telephone D'6C'DC 819-645-3308	
Reported to D'6C'DC BRIAN LAPIERRE		Position, Employer, Location D'6C'DC Spill Line		Telephone D'6C'DC 920-8130	