



NWB Tools

Ida Porter <ida.porter@nwb-oen.ca>

Reportable Spill at Meliadine - December 15th, 2015

Jeffrey Pratt <jeffrey.pratt@agnicoeagle.com>

Wed, Dec 16, 2015 at 10:17 AM

To: Alain Chouinard <achouinard@gov.nu.ca>, "spills@gov.nt.ca" <spills@gov.nt.ca>, "licensing@nunavutwaterboard.org" <licensing@nunavutwaterboard.org>, "Christine.Wilson@aandc-aadnc.gc.ca" <Christine.Wilson@aandc-aadnc.gc.ca>, Luis Manzo <dirlands@kivalliqinuit.ca>, Jeff Tulugak <jtulugak@kivalliqinuit.ca>, "Harmer, Rob" <RHarmer@gov.nu.ca>, Johanne Coutu-autut <JCoutu-autut@gov.nu.ca>, "Erik.Allain@aandc-aadnc.gc.ca" <Erik.Allain@aandc-aadnc.gc.ca>, "Cbeardsaw@kivalliqinuit.ca" <Cbeardsaw@kivalliqinuit.ca>

Cc: Meliadine Environment <meli.environment@agnicoeagle.com>, Kevin Buck <kevin.buck@agnicoeagle.com>, Jason Allaire <jason.allaire@agnicoeagle.com>, Jean Beliveau <jean.beliveau@agnicoeagle.com>, Dominique Girard <dominique.girard@agnicoeagle.com>, Martin Gaumont <martin.gaumont@agnicoeagle.com>, Lonny Syvret <lonny.syvret@agnicoeagle.com>, Eric Cote - Meliadine <eric.cote2@agnicoeagle.com>

Good day,

Attached is a spill report depicting an incident which took place on December 15th, 2015 at Agnico Eagle Mines Ltd., Meliadine Project.

This spill is being reported as required by the conditions under the Nunavut Water Board License 2BB-MEL1424, Part H, item 4 (b) pursuant to subsection 12(3) of the Nunavut Waters and Nunavut Surface Rights Tribunal Act.

This spill is also being reported as required by the Government of Nunavut's, Environmental Protection Act, paragraph 5.1(a).

A follow up report will be submitted following the cleanup actions.

If you require further information or have questions, please do not hesitate to contact the undersigned.

Thank you,

Jeff

Jeffrey Pratt
Environmental Coordinator MBK-MEL

ICMC Facilitator

jeffrey.pratt@agnicoeagle.com

T: 819.759.3555 x6728 (MBK)

T: 819.759.3555 x3928 (MEL)

M: 306.960.2370

Agnico Eagle Mines Limited
Meadowbank Division / Meliadine Division
Baker Lake, Nunavut, Canada / Rankin Inlet, Nunavut, Canada
X0C 0A0 / X0C 0G0

agnicoeagle.com



2 attachments

GN REPORTED SPILL GENSET VALVE FAILURE DEC_15_2015.jpg
467K



GN REPORTED SPILL GENSET VALVE FAILURE DEC_15_2015.pdf
143K