


Report Number
2025-BC-00019

- Well organized camp
- Time was made to allow for inspection and workers were very helpful
- New innovative technology being used (DATS system)
- Using radiation tags as a safety measure



- 2 of 11 -

Inspection Report

Mining

Report Number
2025-BC-00019

Order 2025-BC-00019-001

Required Compliance Date: July 31, 2025

Status: Open

Date of Compliance:

Sub-Location: Drill 1

Observation:

- Eyewash bottle at drill expired

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 9.27. (1)(b):

Where there is potential for injury by eye contact, a manager shall provide, at or near the exposure site, the appropriate hygiene facilities including portable eye wash stations or eye wash fountains and maintained in a hygienic and working condition.



THIS REPORT MUST BE POSTED IN A CONSPICUOUS PLACE

Report Number
2025-BC-00019

Order 2025-BC-00019-002

Required Compliance Date: July 31, 2025

Status: Open

Date of Compliance:

Sub-Location: Drill 1

Observation:

-New Driller (promoted early because of no-show on plane) does not have his WSCC exploration supervisor level I certificate

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 5.03.:

Within one year after these regulations come into force, the manager shall ensure that every person employed at the mine, other than office employees and those employed underground in mines or in open pit operations, is under the supervision of the holder of a supervisor's certificate level 1.

Inspection Report *Mining*

Report Number
2025-BC-00019

Order 2025-BC-00019-003

Required Compliance Date: July 31, 2025

Status: Open

Date of Compliance:

Sub-Location: Drill 1

Observation:

-Flammable waste not being stored in metal container

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 9.11.:

Waste materials containing solvents, grease, paints or other flammable substances shall be stored in covered metal containers while awaiting disposal.



THIS REPORT MUST BE POSTED IN A CONSPICUOUS PLACE

Inspection Report

Mining

Report Number
2025-BC-00019

Order 2025-BC-00019-004

Required Compliance Date: August 31, 2025

Status: Open

Date of Compliance:

Sub-Location: Drill 1

Observation:

- No E-Stop located on the Helpers side of the drill

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 10.04. (1):

The manager shall ensure that a procedure is established for the safe operation, maintenance, inspection and testing of mechanical equipment and any system considered to be dangerous by the committee.

Report Number
2025-BC-00019

Order 2025-BC-00019-005

Required Compliance Date: July 31, 2025

Status: Open

Date of Compliance:

Observation:

- No Barricade to prevent inadvertent access to the wireline

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 10.16.:

Every

- (a) drive belt, chain, rope or cable,
- (b) pulley, sprocket, flywheel or geared wheel,
- (c) opening through which any belt, pulley or wheel operates,
- (d) bolt, key or set screw,
- (e) revolving, reciprocating or relative motion part,
- (f) item projecting from a surface, and
- (g) counter or tension weight unit and travel path, and every other item that has motion or relative motion or is hot or electrically energized shall, unless it is so situated as to prevent a person from coming into accidental contact with it, be effectively enclosed, covered or guarded.



THIS REPORT MUST BE POSTED IN A CONSPICUOUS PLACE

Inspection Report
Mining

Report Number
2025-BC-00019

Order 2025-BC-00019-006

Required Compliance Date: August 15, 2025

Status: Open

Date of Compliance:

Sub-Location: Core Shack

Observation:

-Hot drip stove in walking path with no barricade or identifier to prevent accidental contact in both core shacks

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 1.90.:

Where workers are required to work, operate, maintain or service equipment, a safe means of access shall be provided as required by section 1.89.



THIS REPORT MUST BE POSTED IN A CONSPICUOUS PLACE

Inspection Report

Mining

Report Number
2025-BC-00019

Order 2025-BC-00019-007

Required Compliance Date: July 31, 2025

Status: Open

Date of Compliance:

Sub-Location: Core Shack

Observation:

- No identifier on door to allow incoming personnel to be aware of active splitting in progress

The mine manager shall comply with the following legislation

Mine Health & Safety Regulations

Section 9.05. (2)(a):

The manager shall prepare safe operating procedures for special tasks, which procedures shall include the elimination or minimizing of hazards by engineering controls;



THIS REPORT MUST BE POSTED IN A CONSPICUOUS PLACE

Inspection Report

Mining

Report Number
2025-BC-00019

Regulatory Requirements

This report has been issued pursuant to Section 26 of the Mine Health and Safety Act which states that a closeout meeting will be held with the manager after completing the inspection and that a written report will follow within 72 hours after the last day of the inspection.

Pursuant to section 28 the manager shall post all inspection reports and orders issued by an inspector in a conspicuous place at the mine for at least 30 days after the manager receives the inspection report or order. Furthermore; pursuant to section 29. (1) the manager shall, within 30 days after receiving an inspection report, submit a written report to the Chief Inspector outlining the remedial measures taken and the remedial measures still to be taken in respect of the inspection report.

Pursuant to section 32. (1) A person who is adversely affected by a decision or order issued by an inspector may appeal the decision or order, in writing, to the Chief Inspector within 30 days after its issue

Please return a signed copy of this page as confirmation of receipt.

Received By:

Employer Representative
(Print Name)

Signature

Bryson Cochran

Inspector's Signature

Translation Requests

▷◁ 00^{5b}c ◁▷ Δ^a ◁▷^c Δ^b 0▷^c ▷^b γ^a J^b <C.

Una titiraq piinnarialik Inuinnaqtun piyumayaukpat.

Ce document est disponible en français sur demande.

Inspection Report
Mining

Report Number
 2025-BC-00019

Record of Compliance

1. For each Order, once it is complied with, the Employer must:
 - a. Write in the actions taken towards complying with the Order given;
 - b. Initial the line; and
 - c. E-mail this page to the Mines Inspector on or before the listed compliance date.
2. Once all Orders are complied with, sign the Record of Compliance and e-mail this page to the Mines Inspector.

Order Number	Compliance Required By	Compliance Status	Date	Initials
2025-BC-00019-001	July 31, 2025			
2025-BC-00019-002	July 31, 2025			
2025-BC-00019-003	July 31, 2025			
2025-BC-00019-004	August 31, 2025			
2025-BC-00019-005	July 31, 2025			
2025-BC-00019-006	August 15, 2025			
2025-BC-00019-007	July 31, 2025			

Verified By: _____

Employer Representative
 (Print Name)

Signature