

NWB Annual Report

Year being reported: 2008



License No: 2BE-ANI0813 Issued Date: October 30, 2008
 Expiry Date: October 31, 2013

Project Name: Anialik

Licensee: North Arrow Minerals Inc.

Mailing Address: North Arrow Minerals Inc.
 Suite 204, 4817 - 49th Street
 Yellowknife, NT
 X1A 3S7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

No work was conducted under the authority of this license during the 2008 exploration season.

Licence Requirements: the licensee must provide the following information in accordance with

Select



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

| | | |
|------------------|---|--------------------------------------|
| Water Source(s): | N/A | |
| Water Quantity: | 25 cu.m/day (including drilling) | Quantity Allowable Domestic (cu.m) |
| | N/A | Actual Quantity Used Domestic (cu.m) |
| | 25 cu.m/day (including domestic use) | Quantity Allowable Drilling (cu.m) |
| | N/A | Total Quantity Used Drilling (cu.m) |

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

| |
|--|
| |
|--|

A list of unauthorized discharges and a summary of follow-up actions taken.

 Spill No.: (as reported to the Spill Hot-line)

 Date of Spill:

 Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

| |
|--|
| As no work was conducted under the authority of this license during 2008 there were no occurrences of unauthorized discharges. |
|--|

Revisions to the Spill Contingency Plan

SCP addendum attached for Board consideration



Additional Details:

| |
|---|
| A copy of the Revised Spill Contingency Plan was forwarded to NWB on 17 January 2009. |
|---|

Revisions to the Abandonment and Restoration Plan

AR addendum attached for Board consideration



Additional Details:

| |
|---|
| A copy of the revised Abandonment and Restoration Plan was forwarded to NWB on 17 January 2009. |
|---|

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

| |
|-----|
| N/A |
|-----|

Results of the Monitoring Program including:
The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)



Additional Details:

| |
|-----|
| N/A |
|-----|

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

| |
|-----|
| N/A |
|-----|

| |
|--|
| |
|--|

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

No work was conducted under the authority of this license during the 2008 exploration season and therefore no inspection was conducted.

Any additional comments or information for the Board to consider

| |
|--|
| |
|--|

Date Submitted:

February 14, 2009

Submitted/Prepared by:

Gordon Clarke, President, North Arrow Minerals Inc.

Contact Information:

Tel: (867) 873-8483

Fax: (867) 873-8493

email: gord@northarrowminerals.com