WATER USE INSPECTION REPORT

Date: July 14,2009	Licensee Rep. (Name/Title): None		
Licensee: Pure Diamond	ls	Licence No.:	2BE-BAF

WATER SUPPLY

Source(s): None – Camp inactive at present	Quantity used: None
Owner:/Operator: Pure Diamonds	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems:	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines:	Pumping Stations: NA	Screen : NA

Comments: Camp is inactive at this time. No water consumption. Equipment to pump and water was noted in Camp. No treatment system was noted. Sump has been dug on site and left uncovered. No debris in sump at time of inspection.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): Latrine system- not in use.

Natural Water Body: No	Continuous Discharge (land or water): None		
Seasonal Discharge: None	Wetlands Treatment: None	Trench: None	

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NI	Decant Structure: NA	Erosion: None
Discharge Meas. Device: NI	Dyke Inspection: NA	Seepages: None
Dams, Dykes: NA	Freeboard: NA	Spills: None
Construction: NI	O&M Plan: NI	A&R Plan: NI
Discharge: None	Effluent Discharge Rate: Unknown	

Comments: No human wastes are being generated at the Camp at this time. Human wastes noted in barrel at Storage building between Camp and air strip.

Solid Waste: Food (garbage bags) and other wastes were noted at the airstrip at time of inspection

Owner/Operator: Pure Diamonds

Landfill: None	Burn & Landfill: NA	Other: (Barrels)
----------------	---------------------	------------------

Comments: Wastes are to be removed prior to camp closure.

FUEL STORAGE: Barrel storage at air strip – unsecured- spills noted on site.

Waste Oil Storage: None Owner/Operator: Pure Diamonds

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: U /none	Water within Berms: None	Evidence of Leaks: U
Drainage Pipes: None	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments:. At the airstrip 1 barrel of fuel was noted has having leaked / emptied into the sand on the strip. This is to be reported to the spill line and remediated. None of the drums on site had any secondary containment. Fuel caches must be monitored regularly if fuel is to be overwintered or held on site.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected : 0		Owner /Operator: Annual reports are to be provided when Camp is reactivated.	
0		INAC: No water use or waste was noted on site.	
Signs Posted	ed SNP: None		Warning: None
Records & Reporting: records to be provided in annual report			
Geotechnical Inspection: N/A			

Non-Compliance of Act or Licence: The Pure Diamonds (Pingujuak Camp site) site was not in compliance with the terms and conditions of the License at the time of the inspection. It is required that the inspection and monitoring of fuel caches be done in accordance with the issued license as well as the INAC Fuel Storage Guidelines. Secondary Containment for fuel storage and transfer areas is required.

A.Keim	Sent by E-mail
Inspector's Name	Inspector's Signature