

NWB Annual Report

Year being reported: 2012 ▼

License No: 2BE-BEL1114 Issued Date: June 16, 2011
 Expiry Date: June 16, 2014

Project Name: Belcher Island Diamond Drilling Project

Licensee: Canadian Orebodies Inc.

Mailing Address: 301-141 Adelaide Street West
 Toronto, ON
 M5H 3L5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Canadian Orebodies Inc.

General Background Information on the Project (*optional):

Early stage mineral exploration program targeting iron ore formation.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Unnamed waterbodies near drill sites	
Water Quantity:	3.00	Quantity Allowable Domestic (cu.m)
	0.00	Actual Quantity Used Domestic (cu.m)
	157.00	Quantity Allowable Drilling (cu.m)
	46.61	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☒ Drill Waste
☒ Greywater
☐ Hazardous
☐ Other:

Additional Details:

Daily water usage log attached. See file "2012 Water Usage Records.pdf"
 GPS Coordinates of drill holes, water sources, and drill water return areas provided in file "2012 Water Usage Coordinates.pdf".

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill: 08-21-2012

Date of Notification to an Inspector: 08-23-2012

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Drill return water was routed to an area that was not recognized as an area adjacent to a wetland. The spill was noted by water inspectors Joseph Monteith and Eva Paul and immediate action was taken to move the water hose to a new location in the presence of the inspectors. A spill report was filed on August 23, 2012 by our program geologist Edwin Escarraga (and our water inspectors were copied) but I can't find the spill number.

Revisions to the Spill Contingency Plan

SCP addendum attached for Board consideration



Additional Details:

Fixed reference to AANDC's Manager of Field Operations for reporting hazardous material spills.

Revisions to the Abandonment and Restoration Plan

AR addendum attached for Board consideration



Additional Details:

Added provisions for reclamation of drill holes as suggested by AANDC.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached



Additional Details:

See file "2012 Water Usage Coordinates.pdf"

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached

Additional Details:

See file "2012 Water Usage Coordinates.pdf"

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

Joseph Monteith of INAC visited our site on August 21, 2012. We were advised to supply additional berms to surround any fuel or chemical containers which we subsequently completed shortly thereafter. It was also requested that we clean up the ashes from some material that was open-burned (by someone else) in the area where our former camp was. This was done before the end of the season.

Any additional comments or information for the Board to consider

We did not have a remote camp this year as we rented a portion of the hotel and a house in Sanikiluaq to house our crew, so that is why our domestic water use was 0 this year.

Date Submitted:
Submitted/Prepared by:
Contact Information:

March 13, 2013

Gordon McKinnon

Tel: 416-644-1747

Fax: 416-628-5911

email: gmckinnon@canadianorebodies.com