

NWB Annual Report

Year being reported: 2006 ▼

License No: 2BE-BRO0607 **Issued Date:** March 23, 2006
Expiry Date: December 31, 2007

Project Name: Brodeur Property

Licensee: Kennecott Canada Exploration Inc

Mailing Address: #354-200 Granville St
 Vancouver, BC
 V6C 1S4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Diamondex Resources Ltd., Operator

General Background Information on the Project (*optional):

The camp was occupied by a crew of 12-15 people. Water was used for showers, drinking, and washing dishes.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp	
Water Quantity:	10 cu.m/day	Quantity Allowable Domestic (cu.m)
	1 cu.m/day	Actual Quantity Used Domestic (cu.m)
	50 cu.m/day	Quantity Allowable Drilling (cu.m)
	0 cu.m/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills.

Revisions to the Spill Contingency Plan

No Spill Contingency Plan (SCP) submitted or approved ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

No Abandonment and Restoration (AR) Plan submitted or approved ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

To date there has been no reclamation work undertaken.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

Domestic - 73°14'49', -87°52'10'

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below ▼

Additional Details:

Camp - 73°14'49', -87°52'10'

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 13, 2007

Submitted/Prepared by:

Janet Stritychuk, Land Manager, Diamondex Resources

Contact Information:

Tel: (604) 687 6644

Fax: (604) 687 1448

email: jstritychuk@diamondex.net