

**Strongbow Resources Inc.,
West Kitikmeot Region, Nunavut**

Abandonment and Restoration Plan

Upon completion of the Land Use Operation on the properties subject to the Strongbow/NTI mineral exploration agreement the following steps and procedures will be followed to allow proper abandonment and reclamation of the area:

1. Gray water sumps and sewage pits at the camp will be back-filled.
2. All remaining garbage will be incinerated in a burn barrel.
3. All wood (tent floors, frames etc.) will be burned. The coals and ash will be raked for non-combustible items (i.e. nails etc) which will be collected and removed from the site. The remaining coals will be buried.
4. All camping materials, fuel drums, and drilling equipment (if applicable) will be removed from the site.
5. If the drilling program is conducted, all drilling sumps will be back-filled, burying the cuttings and sludges.
6. Each drill site will be inspected to ensure that all garbage (combustible and non-combustible) has been collected and removed from the area.
7. A last inspection will ensure that there is no remaining material at the site and that there is little/no evidence for Strongbow's land use activity.