

17......

WATER LICENCE INSPECTION FORM

\boxtimes	Original	
	Follow-Up	Report

Licensee				LICEIISEE NE	icensee kepresentative				
Peregrine Diamonds Ltd			Dave Willis						
Licence No. / Expiry			Representative's Title						
2BE-CHI1218			Land Administrator						
Land / Other Authorizations	Land / Other Authorizations			Land / Other Authorizations					
N2012C0024									
Date of Inspection	Date of Inspection			Inspector					
17/07/15				Justin	HACK				
Activities Inspected	_								
☐ Camp ☐ Roads/Hauling ☐	Drilling Other: Cu	lvert			nstruction X Reclamation ner: Bridge		★ Reclamation	☐ Fuel Storage	
									_
	ceptable			- Unaccept	able	NA –	Not Applicable	NI – Not Ins	pected
Water Use	Condition	Comment	Site Conditions		Condition	Comment	Haz/Mat Managem	nent Condition	Comment
Intake/Screen	NI		Water Management S	tructures	С	4	Storage	NI	
Flow Measure. Device	NI		Culverts / Bridges		NA		Spills	NI	
Source:	Α		Drainage		NA		Spill Plan	NI	
Water Use:	NI		Erosion / Sediment		Α				
Recirculation (y /n)	NI		Mitigation Measure	!S	NA		Administrative		
			Reclamation Activiti	ies	NA		Records	NA	
			Materials Storage		Α		Reports	А	
Waste Disposal			Signage		NI		Plans	А	
Waste Water	С	5					Notifications	NA	
Solid Waste	С	6	Monitoring				Other		
Hazardous Waste	Α		Sample Collection /	Analysis	NA				
*The number in the comments field will correspond with specific comments provided below.									
Samples taken by Inspector: Location(s):			Location(s):						
☐ Yes ⊠ No									

SECTION 1	Comments (s.1)	Non-Compliance with Act or Licence (s)	Action Required (s.)
JECTION I		i von compliance with Act of Electrice (5.)	Action Required (5.

Background

Nunavut Water Licence #2BE-CHI1218 was issued to Peregrine Diamonds Ltd on February 8, 2012 for the use of 95 cubic metres of water per day and the disposal of waste for camp operations and activities related to exploration including diamond drilling, large diameter reverse-circulation drilling, and other associated activities.

Water Use and Waste Disposal is authorized through this licence at the Chidliak Project, supported from the Discovery, Sunrise, Aurora, CH-6 Camps located on the Hall Peninsula.

Inspector's Statement

On July 17, 2015 a water licence inspection was conducted for water licence 2BE-CHI1218. Sites visited included the Discovery, Sunrise, Aurora and CH-6 campsites, Drill Waste Disposal Area and nearby drill sites. At the time of inspection, the camp was inactive; however, Peregrine Diamonds Ltd had the camp operational shortly after the inspection for use in summer 2015.

Observations:

Direct Water Use

- 1. Domestic and Drilling Purposes
 - a. No water was being used at the time of inspection.
- 2. Water Sources
 - a. No concerns

Water Management Structures

- 3. Secondary Containment Structures
 - a. Secondary containment was present for the storage of hazardous materials at the camps. Larger secondary containment structures that were storing fuel had an SEI Industry, RainDrain attached to the lower end of the structure to filter out hydrocarbons. No fuel leaks were apparent within these structures. The proponent is reminded that ongoing maintenance of these temporary structures is required to ensure their integrity.
 - b. Smaller secondary containment surrounding fuel tanks attached to camp tents were working as intended. Many of these structures are not covered and require annual maintenance to prevent over-topping of water.
- 4. Drill Waste Disposal Area
 - a. The drill waste disposal area is an area of concern. As detailed in the Licence, all drill waste must be deposited into a properly constructed sump or natural depression that prevents discharges into the environment. It is recommended that Peregrine re-evaluate this location and determine that all water from this facility can be controlled and discharged as required while meeting the discharge criteria limits in the licence. A follow-up



*

inspection of this site will be conducted in 2016.

Waste Disposal

- 5. Drill Waste Disposal Area
 - a. Potential concern related to the uncontrolled discharge from the Drill Waste Disposal Area. All discharges from this facility must be controlled and must meet discharge criteria as determined within the licence.
- 6. General Waste Management at Camp
 - a. Small concerns related to the management of ash produced from incineration. Please ensure all ash is properly contained and managed to prevent it from entering water. In a follow-up phone call after the inspection, Peregrine identified that this concern was addressed. This will be confirmed at the next water licence inspection during the summer of 2016.

Click here to enter text.				
SECTION 2 Comments (s2_) Non-Compli	ance with Act or Licence, (s) Action Required (s)			
L				
Licensee or Representative	Inspector's Name			
	Justin Hack			
Signature	Signature			
Date	Date			
	21/10/2015			

		21/10/2013		
Office Use Only:	Follow-up report to be issued by Inspector		⊠Yes □ No	

