

WATER USE INSPECTION REPORT

Date: August 1,2009	Licensee Rep. (Name/Title): None
Licensee: Shear Minerals	Licence No.: 2BE-CHU0813

WATER SUPPLY

Source(s): Josephine Lake		Quantity used: None	
Owner:/Operator: Shear Minerals		None – Camp inactive at present	
Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected			
Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: Camp is inactive at this time. No water consumption. Equipment to pump and treat water are stored on site for when and if Camp is reactivated.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): N/A

Natural Water Body: No	Continuous Discharge (land or water): None	
Seasonal Discharge: None	Wetlands Treatment: None	Trench: None

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Discharge Quality: NI	Decant Structure: NA	Erosion: None
Discharge Meas. Device: NA	Dyke Inspection: NI	Seepages: None
Dams, Dykes: A	Freeboard: NA	Spills: NI
Construction: NI	O&M Plan: A	A&R Plan: A
Discharge: None	Effluent Discharge Rate: Unknown	

Comments: No human wastes are being generated at Camp at this time.

Solid Waste: No wastes generation was noted on site at the time of Inspection (

Owner/Operator: Shear Minerals

Landfill: None	Burn & Landfill: NA	Other: (Barrels)
----------------	---------------------	------------------

Comments: No waste is currently generated on site.

FUEL STORAGE: Barrel storage

Waste Oil Storage: Not determined Owner/Operator: Shear Minerals

Indicate: A - Acceptable U - Unacceptable NA - Not Applicable NI - Not Inspected

Berms & Liners: A	Water within Berms: U	Evidence of Leaks: None
Drainage Pipes: None	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: NA	

Comments: A number of barrels both in and outside of secondary containment are stored on site, at the runway and one other cache located during the Inspection. Location of any other caches is unknown. Licensee is to provide records of monitoring of fuel caches as required under the 2008 Direction as issued.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected : 0	Owner /Operator: Monthly reports are to be provided when Camp is reactivated.	
0	INAC: No water use or waste was noted on site.	
Signs Posted	SNP: None	Warning: None
Records & Reporting: records to be provided in annual report		
Geotechnical Inspection: N/A		

Non-Compliance of Act or Licence: It is highly recommended that the licensee ensures that continuation of monitoring inspections on fuel caches on the property is maintained as required. Water within the secondary containment must be treated prior to discharge. Sampling results are to be provided to the Inspector.