



Indian and Northern Affairs Canada
Affaires Indiennes et du Nord Canada

INDUSTRIAL WATER USE INSPECTION REPORT

DATE: Aug, 25/05 COMPANY REP.: Allen Keshburgh
 LICENSEE: Committee Bay Resources Ltd. LICENCE #: NWISLCRA0507

WATER SUPPLY

Source: Hayes Lake Quantity Used: _____ Meter Rdg.: _____

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Intake Facilities <u>U</u>	Storage Structures _____	Treatment Systems _____	Recycling _____
Flow Meas. Device <u>NA</u>	Conveyance Lines _____	Pumping Stations _____	Modifications _____

Comments: Water from Hayes Lake is not treated. The intake pump is right at the lakes edge. The pump should be > 30m from the lakes edge and it must have a drip pan & a spill kit to prevent contamination of Hayes Lake. Water use should be tracked on a daily basis

WASTE DISPOSAL

Tailings: NA Tailings Pond ☐ Natural Lake ☐ Underground ☐

Sewage: Incinerated Sewage Treat. System ☐ Tailings Pond ☐ Natural Water Body ☐
 Continuous Discharge ☐ Inter. Dischg. ☐

Solid Waste: Incinerated/transported off-site Open Dump ☐ Landfill ☐ Burn & Bury ☐ Underground ☐

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Discharge Quality <u>Sampled</u>	Conveyance Lines <u>NA</u>	Disch. Meas. Dev. <u>NA</u>	Freeboard <u>NA</u>
Decant Structures <u>NA</u>	Pond Treatment <u>NA</u>	Dams, Dykes <u>NA</u>	Seepage <u>NA</u>
Dyke Inspections <u>NA</u>	Runoff Diversion <u>NA</u>	Erosion <u>NA</u>	Spills <u>NA</u>

Effluent Discharge Rate: _____ Samples Collected: _____

Comments: The camps sleeping tents are too close to a creek running into the adjacent lake. The heating fuel for the sleeping tents, the generator stack, the greywater discharge and the small fueling station in camp are all < 30m from the water.

GENERAL CONDITIONS

Indicate: A - Acceptable U - Unacceptable N/A - Not Applicable

Ore & Waste Rock Stockpiles <u>NA</u>	Records & Reporting <u>NA</u>	Surv. Net. Prog. <u>NA</u>
Geotechnical Inspection <u>NA</u>	Posting, Signage <u>NA</u>	Contingency Plan <u>(#)</u>
Restoration Activities <u>NA</u>	New Construction <u>NA</u>	Fuel Storage _____
Mine Water Discharge <u>NA</u>	Chemical Storage <u>NA</u>	Annual Report _____

Comments: All fuel heating fuel drums should have secondary containment, the generators should have drip pans & all buildings & greywater discharge should be > 30m from (water) surface water. The incinerator itself also be moved.

Violations of Act or Licence: Fuel is located too close to a water body as is the greywater sum/fueling station & incinerator. None of these structures can remain where they are. They must be an effective 70m away from a water

General Comments: (attach pg. 2 if req'd.) A containment body to minimize the potential for contamination of water. Silt fences in the stream adjacent to the greywater discharge & fuel & a berm around the incinerator show some promise for water in the area unfortunately these mitigating measures Page 2 attached ☒ Yes ☐ No

Project Manager
Licensee Representative's Title

[Signature]
Licensee Representative's Signature

SCOTT STEWART
Inspector's Name

[Signature]
Inspector's Signature

Nunavut Water Board

OCT 11 2005

Public Registry

Indian and Northern
Affairs CanadaAffaires indiennes
et du Nord Canada

INDUSTRIAL WATER USE INSPECTION REPORT

(continued)

Date: Aug 25/05Licence #: NW82CRA0507

General Comments: (Continued)

do not satisfy the terms and conditions of the water licence. Please relocate the structures mentioned in the report to a location $>30m$ from water & send pictures to the Inspector identifying the new locations. The structures must be moved by the summer of 2006. The camp should put in secondary containment structures for heating fuel tanks. I will provide pictures of the "crates" used at Goose Lake.

Water Inspector