

NWB Annual Report

Year being reported:

2014 ▼

License No: 2BE-CRA 1015

Issued Date:

April 1, 2010

Expiry Date:

March 31, 2015

Project Name:

Committee Bay Project

Licensee:

North Country Gold Corp.

Mailing Address:

220-9797 45th Avenue
Edmonton, AB, Canada
T6E5V8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

As above

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Sandspit Lake

Water Quantity:

50 cu.m/day

8.6 cu.m total

245 cu.m/day

0.0 cu.m

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☒ Solid Waste Disposal☒ Sewage☒ Drill Waste☒ Greywater☒ Hazardous☐ Other:

Additional Details:

Total of 8.6 cubic metres used for camp (showers/kitchen) in 2014 season.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

14-289

(as reported to the Spill Hot-line)

Date of Spill: [before 20 July 2014](#)

Date of Notification to an Inspector: [July 20, 2014](#)

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

[Spill was identified by inspector. NCGC completed spill report on 7 Aug 2014. Spill was addressed upon arrival at site \(~12th August 2014\). Details attached in Remedial Action Report submitted to NWB 30th September 2014.](#)

Revisions to the Spill Contingency Plan

Other: (see additional details)

Additional Details:

[A revised and updated spill contingency plan has been filed as part of NCGC's 2015 water licence renewal application.](#)

Revisions to the Abandonment and Restoration Plan

Other: (see additional details)

Additional Details:

[A revised and updated Abandonment and Restoration plan has been filed as part of NCGC's 2015 water licence renewal application.](#)

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

[Crater camp was dismantled and backhauled back to Hayes Camp in the summer of 2012. NCGC will inspect and conduct additional cleanup of this site in subsequent operational seasons. Ongoing reclamation will include inspections and cleanup of drill sites \(where necessary\).](#)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached

Additional Details:

[Please see attached "GPS Coordinates" for water sources used in 2014.](#)

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached



Additional Details:

Please see attached "GPS Coordinates" for waste disposal sites used in 2014.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Annual sampling of water monitoring stations CRA-1, CRA-2 and CRA-3 was completed. Please see NCGC 2014 Annual Report for details and results.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Not Applicable

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

The Committee Bay Project was inspected by AANDC Water Resources Officer on the 20th July 2014. NCGC addressed deficiencies raised during the inspection and provided a report titled "Remedial Action Report - Detailing work completed to address 2013 Land Use Inspection Report and 2014 Water Licence Inspection Report" on the 30th September 2014. Additional information on outstanding items are included in the NCGC 2014 Annual Report.

Any additional comments or information for the Board to consider

Date Submitted:	10-Dec-2014
Submitted/Prepared by:	Simeon Robinson
Contact Information:	Tel: 780 437 6624 (office) 780 616 9459 (cell)
	Fax: 780 439 7308
	email: simeonr@northcountrygold.com



GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	° Deg	' Min	'' Sec	° Deg	' Min	'' Sec
Hayes Camp - Sandspit Lake	66	39	27.78	91	33	10.85

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude		
	° Deg	' Min	'' Sec	° Deg	' Min	'' Sec
Hayes Camp - Greywater sump	66	39	30.66	91	33	5.70
Hayes Camp - Incinerator	66	39	29.96	91	33	5.89
Hayes Camp - Quanset 2 (Haz waste)	66	39	41.60	91	33	9.21