

NWB Annual Report

Year being reported:

Select



2015

License No: 2BE-CRA 1520

Issued Date:

March 4, 2015

Expiry Date:

March 3, 2020

Project Name:

Committee Bay Project (CBP)

Licensee:

North Country Gold Corp. (NCGC)

Mailing Address:

600-1199 West Hastings Street
Vancouver, BC
Canada, V6E3T5

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

North Country Gold Corp / Auryn Resources Inc

General Background Information on the Project (*optional):

In September 2015, Auryn Resources Inc acquired NCGC. NCGC remains the operator of the CBP as a wholly owned subsidiary of Auryn.

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 2



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Sandspit Lake (Hayes Camp) / Unnamed river (Bullion Camp)

Water Quantity:

50 cu.m/day

Quantity Allowable Domestic (cu.m)

134 cu.m total

Actual Quantity Used Domestic (cu.m)

245 cu.m/day

Quantity Allowable Drilling (cu.m)

0.0 cu.m

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal



Solid Waste Disposal



Sewage



Drill Waste



Greywater



Hazardous



Other:

(See attached Annual report document for details)

Additional Details:

Total of 134 cubic metres used at Hayes and Bullion Camp in 2015.
Hayes Camp: 42.8 cu.m / Bullion Camp: 91.2 cu.m

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:

(as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No Spills reported during 2015.

Revisions to the Spill Contingency Plan

Other: (see additional details) ▼

Additional Details:

A revised and updated spill contingency plan (NCGC Spill Prevention and Response Plan - Revision 3) is included with this report.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Progressive reclamation in 2015 comprised:
 - Removal of two berms and fuel from Three Bluffs drilling area
 - Clean up and back haul of non-essential materials at the West Plains cache to Hayes Camp for backhaul and disposal

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached ▼

Additional Details:

Please see attached "GPS Coordinates" for water sources used in 2015.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached ▼

Additional Details:

Please see attached "GPS Coordinates" for waste disposal sites used in 2015.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Water samples collected from CRA-1, CRA-2 and CRA-3 (Hayes Camp) and draw point (Bullion Camp) was completed. See Annual report document.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection Report received by the Licensee (Date): ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Water Licence Inspection completed 21 July 2015. Detail of the Inspection Report is included in Annual Report document (attached).


- All issues raised in 2015 Water Licence Inspection have been addressed
- Outstanding issues from 2014 Water Licence Inspection have been addressed.

This included:

- a) Waste backhaul of hazardous wastes (completed April-May 2015)
- b) Remedial actions taken to address issues with Hayes Camp airstrip (completed July-August 2015, work will be ongoing)

Any additional comments or information for the Board to consider

Date Submitted:	30-Oct-2015
Submitted/Prepared by:	Simeon Robinson
Contact Information:	Tel: 778 729 0600 (office) 604 790 8811 (cell)
	Fax: 778 729 0650
	email: Simeon.Robinson@AurynResources.com



GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	Deg °	Min ,	Sec "	Deg °	Min ,	Sec "
Hayes Camp - Sandspit Lake	66	39	27.78	91	33	10.85
Bullion Camp - Unnamed river	66	23	47.15	93	7	36.68

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude		
	Deg °	Min ,	Sec "	Deg °	Min ,	Sec "
Hayes Camp - Greywater sump	66	39	30.66	91	33	5.70
Hayes Camp - Incinerator	66	39	29.96	91	33	5.89
Hayes Camp - Quanset 2 (Haz waste)	66	39	41.60	91	33	9.21
Bullion Camp - Greywater Sump	66	23	49.28	93	7	39.52
Bullion Camp - Latrine 1	66	23	49.48	93	7	39.79
Bullion Camp - Latrine 2	66	23	51.20	93	7	42.20