

**RECEIVED***By Ida Porter at 1:16 pm, Apr 19, 2011*

NWB2(insert)

NWB Annual Report

Year being reported: 2010



License No: 2BE-DBY1014

Issued Date: January 7, 2010

Expiry Date: December 31, 2014

Project Name: Darby Project

Licensee: Indicator Minerals Inc.

Mailing Address: Suite 275-1075 West Georgia Street  
Vancouver, BC Canada  
V6E 3C9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Teck Resources Limited (partners on the Darby Project)

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Select



.....



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Water Quantity:

32 cu.m/day

0

0

Quantity Allowable Domestic (cu.m)

Actual Quantity Used Domestic (cu.m)

Quantity Allowable Drilling (cu.m)

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal☐ Sewage☐ Drill Waste☐ Greywater☐ Hazardous☐ Other:

Additional Details:

No work program was conducted in 2009, hence there was no water usage and no waste generation during this reporting period.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (NA)



Additional Details:

No work program was conducted in 2010, hence there was no water usage.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (NA)



Additional Details:

No work program was conducted in 2010, hence there was no waste generated.

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

Inspection Report received by the Licensee (Date):



Additional Details: (Dates of Report, Follow-up by the Licensee)

An inspection report was received by Indicator Minerals on 17 February 2011.  
No follow-up has been completed due to site inaccessibility during winter.

**Any additional comments or information for the Board to consider**

Accompanying this report are photographs of the existing Stellar Camp, located on the Darby Property.

**Date Submitted:**

March 25, 2011

**Submitted/Prepared by:**

Indicator Minerals Inc/Karen-Jane Weir

**Contact Information:**

**Tel:** 604.699.4149

**Fax:** 604.699.4724

**email:** [karen.weir@teck.com](mailto:karen.weir@teck.com)