Material Safety Data / Fiche signalétique

WESTCOAST DRILLING SUPPLIES LTD.

8069 River Way, Delta, British Columbia,

Canada V4G 1L3

Ph. (604) 940-6050 Fax (604) 940-6080

EMERGENCY 1-800-665-6645

	SEC	TION I. II	PNTIFICAT	TION OF PRODUCT	
	SEC	110111. 11	DENTIFICA	HON OF FRODUCT	
PRODUCT NAME:			KOPR K	COTE	
CHEMICAL FAMI WHMIS CLASSIFION			Petroleum Based Thread Compound Not regulated		
WORK PLACE HA			Not available		
	TRANSP	ORTATIO	N OF DANG	EROUS GOODS (TDGR)
CLASSIFICATION			Non Hazardous For Transportation		
PACKAGE GROUP			Not applicable		
PRODUCT IDENTI	FICATION NUMBI	ER (PIN):	Not available		
	SE	CTION II:	HAZARDO	US INGREDIENTS	
INGREDIENT	PERCENTAGE	CAS NU	JMBER	OSHA PEL	ACGIH TLLV
Petroleum Oil	70M	64742-57-0 or 64742-62-7		Oil Mist	Not applicable
				$TWA - 5 mg/m^3$	
Lead Powder	15M	7439-92-1		Air - 200 ug/M ³	Air - 0.15 mg/M^3
Copper	10M	7440-50-8		N/A	1 mg/M ³
	SECT	TION III: 7	roxicolo(GICAL PROPERTIES	
ROUTE OF ENTRY	-				
[] Skin []	Eye Contact []	Inhalation	[] Ing	gestion	
SKIN IRRITANCY			: Very mild		
EYE CONTACT : May ca				irritation	
INHALATION : Not available					
INGESTION : May cause diarrhea					
SYMPTOMS OF EX			: Redness and irritation of skin		
EFFECTS OF OVE	REXPOSURE		: Repeated skin contact for persons hypersensitive to petroleum products can cause redness and irritation of skin.		
MEDICAL CONDI	TIONS POTENTIAL	īv	products	an cause reuness and mina	tion of skin.
AGGRAVATED B		-L- 1	: Unknown		
MATERIAL LISTE		N	. Olkhown		
OR POTENTIAL C			: National To	oxicology Program - No. IA	ARC - No. OSHA -No
		SECTION :	IV: FIRST	AID MEASURES	
GWDI GOVERA CE			. n. '		J -1 C-11 J b
SKIN CONTACT EYE CONTACT				by wiping, or waterless hand In copious quantities of water	d cleaner, followed by washing er
PIP CONTUCT			. ** #211 WIU	a copious qualitities of wall	C1.

Clear air passages, call a physician.

Not applicable.

DO NOT induce vomiting, call a physician.

OTHER INSTRUCTIONS

INHALATION

INGESTION

Material Safety Data / Fiche signalétique

WESTCOAST DRILLING SUPPLIES LTD.

8069 River Way, Delta, British Columbia. Canada V4G 1L3 Ph. (604) 940-6050 Fax (604) 940-6080

EMERGENCY 1-800-665-6645

KOPR KOTE

Page 2 of 3

SECTION V: PHYSICAL DATA

APPEARANCE AND ODOUR : Copper colored paste; petroleum odour.

DENSITY (SPECIFIC GRAVITY) : 1.23 **BOILING POINT** : 370 ° C **MELTING POINT** : Not applicable

WATER SOLUBILITY : None % VOLATILE BY VOLUME : None

EVAPORATION RATE : < 0.01 KPA VAPOR PRESSURE (mm Hg) : < 0.01 KPA VAPOR DENSITY (Air = 1) : > 5.0

: Neutral pН VISCOSITY : 1.10 kg/liter

SECTION VI: FIRE AND EXPLOSION HAZARD DATA

FLASH POINT : 294° C (COC Method)

FLAMMABLE LIMIT : LEL = 0.9% UEL = 7%

: > 360° C **AUTO-IGNITION TEMPERATURE**

EXTINGUISHING MEDIA : Use foam, dry chemical, water spray (fog), carbon dioxide CO₂, or

vaporizing liquid type extinguishing agents.

: Use supplied air breathing equipment for enclosed or confined spaces. SPECIAL FIRE FIGHTING PROCEDURES

UNUSUAL FIRE AND EXPLOSION HAZARDS

SECTION VII: REACTIVITY DATA

STABLE [XXX] UNSTABLE [Under normal conditions

INCOMPATIBILITY (conditions to avoid) : Strong oxidizing materials and copper reactive agents.

Incompatible with 1-bromo-2 propyne, NH₄ NO₃, CLF₃, H₂O₂,

NaN₃, Na₂C₂, Zr

HAZARDOUS DECOMPOSITION PRODUCTS : Hydrogen, carbon monoxide, aldehydes, smoke, toxic fumes and

toxic copper and lead compounds.

HAZARDOUS POLYMERIZATION : Will not occur [XXX] May occur []

SECTION VIII: PREVENTATIVE MEASURES

RESPIRATORY PROTECTION : None required.

VENTILATION : No special ventilation required.

PROTECTIVE GLOVES : Protective gloves for hypersensitive persons : Protective glasses if applied to moving parts. **EYE PROTECTION**

OTHER PROTECTIVE EQUIPMENT : Persons with hypersensitive skin should use gloves.

PERMISSIBLE CONCENTRATIONS : Not available

Material Safety Data / Fiche signalétique

WESTCOAST DRILLING SUPPLIES LTD.

8069 River Way, Delta, British Columbia, Canada V4G 1L3 Ph. (604) 940-6050 Fax (604) 940-6080 EMERGENCY 1-800-665-6645

KOPR KOTE

Page 3 of 3

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE

Normal precautions as with any petroleum product.

Wash hands before eating.

Do not allow to enter drains.

STEPS TO BE TAKEN IN CASE OF SPILL OR LEAK

Scoop up excess, wipe with rags, pick up residue with diatomaceous earth to avoid walking hazard.

WASTE DISPOSAL METHOD

Consult federal, provincial/state and local regulations for petroleum products.

SECTION IX: PREPARATION

The information contained herein is given in good faith, but no warranty, expressed or implied is made.

DATE ISSUED: May 25, 1991 BY: Product Safety Committee DATE REVISED: November 2, 2000

Keview date

Authorized