NWB Annual Report	Year being reported: 2008 ▼				
License No: 2BE-EDE-0608	Issued Date: June 7, 2006				
	Expiry Date: December 31, 2008				
Project Name:	EDEHON LAKE, KIVALLIQ REGION - KEEWATIN				
<u> </u>					
Licensee: TRI	ORIGIN EXPLORATION LTD				
Mailing Address:	405 DONLING OOK DRIVE LINE 19				
Maining Address.	125 DON HILLOCK DRIVE, UNIT 18 AURORA, ON				
	L4G 0H8				
Name of Company	y filing Annual Report (if different from Name of Licensee pleas	e clarify			
relationship between	the two entities, if applicable):				
General Background Information	on on the Project (*optional):				
No work done in 20	08				
Licence Requirements: the lice with	nsee must provide the following information in accoda	nce			
Part B ▼	Item 2 ▼				
Acummaninarado de vatarios	and waste disposal activities, including, but not limite	n to methods of			
	reywater management, drill waste management, solid a				
waste management		and a			
Water Source(s):	N/A				
Water Quantity:	Quantity Allowable Domestic (cu.m)				
	N/A Actual Quantity Used Domestic (cu.m)				
	< 85 cu m Quantity Allowable Drilling (cu.m) N/A Total Quantity Used Drilling (cu.m)	Nunavut Water			
	Total Quantity Used Drilling (Cd.111)	Board			
Waste Manageme	•				
Solid Waste D	isposal	JUL 1 & 2011			
Sewage		_ , , , , _ , , ,			
Drill Waste	'	Public Registry			
Greywater					
Hazardous					
Other:					
Additional Details:	AND OUTS MANAGED BY HENRY LAVE ADVENTUDED ED	1014			
	AMP SITE MANAGED BY HENIK LAKE ADVENTURES FR	i			
ARVIAT. WATER LICENCE NO 3BC-EDE-0611, LAND USE PERMIT N2006J0030					
· · · · · · · · · · · · · · · · · · ·					
A list of unauthorized discharg	es and a summary of follow-up actions taken.				

	Spill No.:	N/A	(as reported to the Spill Hot-line)	
	Date of Spill:	IN/A cation to an Inspecto		
		•	mitigation measures, short/long term monitoring, etc)	
	<u> </u>			
Revisions to	the Spill Con	tingency Plan		
	Select			▼
	Additional De	tails:		
				<u></u>
Revisions to	the Abandon	ment and Restora	tion Plan	
	Select			▼
	Additional De	tails:		
Progressive		Work Undertaken		S (4)40, 11, 14, 14, 15, 11, 11, 11, 11, 11, 11, 11, 11, 11
			pleted and future works proposed)	
	NO WORK D	OONE AT ALL IN 20	08; SITES LEFT CLEAN AS IN 2007 REPORT	
Results of the	ie Monitoring	Program including		
	The GPS Co-	-ordinates (in degr	ees, minutes and seconds of latitude and long	gitude) of
		n where sources o	f water are utilized;	
	Select			▼
	Additional De	tails:		
	N/A			
			ees, minutes and seconds of latitude and long sociated with the licence are deposited;	gitude) of
	Select	ii wilete wastes as	Sociated with the incence are deposited,	▼
	Additional De	tails:		
	N/A			
	1			1

Results of any additional sampling and/or analysis that was requested by an Inspector No additional sampling requested by an Inspector or the Board Additional Details: (date of request, analysis of results, data attached, etc) Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported. No additional sampling requested by an Inspector or the Board Additional Details: (Attached or provided below) Any responses or follow-up actions on inspection/compliance reports No inspection and/or compliance report issued by INAC Additional Details: (Dates of Report, Follow-up by the Licensee) Any additional comments or information for the Board to consider No work is planned for 2009 June 20, 2011 **Date Submitted:** Camille Spencer / R Valliant Submitted/Prepared by: **Contact Information:** Tel: 905 727 1779 905 727 8779 Fax:

email: explore@triorigin.com