

NWB Annual Report

Year being reported: Select ▼

License No: 2BE -EDE- 0608 **Issued Date:** June 7, 2006
Expiry Date: tri origin exploration ltd

Project Name: EDEHON LAKE, KIVALLIQ REGION - KEEWATIN PROJECT

Licensee: TRI ORIGIN EXPLORATION LTD

Mailing Address: 3 CENTRE ST, SUITE 206
 MARKHAM
 ONTARIO, L3P 2P9

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

SURFACE GEOLOGICAL SURVEYING AND SAMPLING. PRELIMINARY SHALLOW DRILL PROGRAM OF 7 HOLES - ONLY 98 METRES OF DRILLING COMPLETED.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	EDEHON LAKE, LOCAL PONDS/LAKES AT DRILL SITES	
Water Quantity:	100 cu m/day	Quantity Allowable Domestic (cu.m)
	< 15 cu m	Actual Quantity Used Domestic (cu.m)
	< 85 cu m	Quantity Allowable Drilling (cu.m)
	<3 cu m	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☒ Sewage
- ☒ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

EDEHON LAKE CAMP SITE MANAGED BY HENIK LAKE ADVENTURES LTD FROM ARVIAT (Land Use Permit No. N2006J0030).

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

N/A - not applicable



Additional Details:

Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Drill sites restored to pre-drilling condition. Decant drill water filtered through sands in natural depressions. Foreign materials removed from site.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

EL-06-01	585,002E / 6,701,901N	EL-06-02	587,982E / 6,711,954N
EL-06-03	594,196E / 6,704,910N	EL-06-04	594,229E / 6,704,921N
EL-06-06	588,547E / 6,709,338N	EL-06-06	588,547E / 6,709,338N
EL-06-07	588,547E / 6,709,338N		

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)



Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 29, 2007

Submitted/Prepared by:

AJ Chapman/ R Valliant

Contact Information:

Tel: 905 294 9942

Fax: 905 294 9943

email: explore@triorigin.com