

NWB Annual Report

Year being reported: 2009



License No: 2BE-GEO0510 **Issued Date:** July 3, 2002
Expiry Date: December 31, 2010

Project Name: George Lake Project

Licensee: Sabina Gold & Silver Corp.

Mailing Address: 930 West 1st Street, Suite 202
 North Vancouver, BC V7P 3N4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

The George Lake Project is located approximately 100 km south of the hamlet of Bathurst Inlet, with the camp located at 65°55'13" N, 107°27'35" W.

Licence Requirements: the licensee must provide the following information in accordance with

Part B

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	NA for 2009	
Water Quantity:	140 m3/day	Total Quantity Allowable (cu.m)
	0 m3/day	Actual Quantity Used Domestic (cu.m)
		Quantity Allowable Drilling (cu.m)
	0 m3/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

☐ Other:

Additional Details:

There were no activities involving water use or waste disposal at the George Lake camp in 2009. The camp was opened for a brief period in May and operated by Discovery Mining Services personnel to allow for the repositioning of supplies to Goose Lake. During the active field season (July-September) personnel were on site for short periods with no overnight stays to prepare equipment for use during the winter road at the start of the 2010 season and to carry out routine maintenance. Any minor amounts of waste generated such as food or packaging was transported back to either Hackett or Goose camps for disposal with the regular waste stream.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Other: (see additional details)



Additional Details:

An updated Spill Contingency Plan for 2010 was submitted with the application for renewal on December 3, 2009. Approval has not yet been received.

Revisions to the Abandonment and Restoration Plan

Other: (see additional details)



Additional Details:

An updated Abandonment and Restoration Plan for 2010 was submitted with the application for renewal on December 3, 2009. Approval has not yet been received.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 31,2010

Submitted/Prepared by:

Dan Russell, P.Geo

Contact Information:

Tel: 604-998-4175

Fax:

email: drussell@sabinagoldsilver.com