

INUNGNIK TUHAQTITTIJUT TUKHIUNMIK LAISITAGUMAYUMIT

Nunavut Imalirinirmut Katimayiit piyut uminga tukhiunmik laisitagumayumit:

Laisilik: **Miramar Bathurst Resources Ltd.**
300 – 889 Harbourside Drive
North Vancouver, BC V7P 3S1

Tuniyauquyauyuq: **Dundee Precious Metals Inc.**
Suite 3060, Royal Bank Plaza, South Tower, 200 Bay Street
Toronto, ON M5J 2J1

Atia Havakhap: Goose Lake-mi Havarvik
Nunauyami Huqpaniinnia: Latitude: 65°35'N; Longitude: 112°25'W

Nunavut Imalirinirmut Katimayit piumayut titigarhimayunik uqauhikhanik haffuma mighaagut inungnit ilauyunillu timiuyunit. Turaqtillugit uqauhikhahi **titigarhimalugit** August 5, 2005 hivuagut uvunga:

Manager of Licensing
Nunavut Water Board
P.O. Box 119, Gjoa Haven, Nunavut X0B 1J0
Hivayauta: (867) 360-6338; Kayumikturuta: (867) 360-6369;
Qarittauyakkut: licensing@nwb.nunavut.ca

Atjinngit tukhiutip titiqqat pinnagialgit aktumayauniaqtunit timiuyunit, akiittumik turaqvigilugu:

John Laitin, Dundee Precious Metals Inc.
Hivayauta: (416) 365-5191; Kayumikturuta: (416) 365-9080
Qarittauyakkut: jlaitin@dundeeprecious.com

Tunihinngitkuvit titigarhimayumik uqauhikhaffingnik hivuagut titigarvikhap ayurnautauttaqtuq kinguagut uqaqtitauyami, tunihiyami titiqqanik, uqaqtitauluniluunniit Nunavut Imalirinirmut Katimayiinnut, uvvalu ayunngityutit himmauhiqtauyami tammaqtaqtuq, ilulikkut Iluia 59-kut 60(2)-kullu Maligarmi.