

NWB Annual Report

Year being reported: 2007 ▼

License No: 2BE-HEE0712 **Issued Date:** September 27, 2007
Expiry Date: September 30, 2012

Project Name: Heeqou Property

Licensee: Diamondex Resources Ltd.

Mailing Address: P.O. Box 11584
 1410 - 650 West Georgia Street
 Vancouver, BC
 V6B 4N8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Same as Licensee

General Background Information on the Project (*optional):

The Heeqou camp was not occupied during 2007. No work was conducted, therefore no water was used and no waste deposited.
 The water license was renewed to 2012.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Domestic - unnamed lake adjacent to the camp, Drilling - local	
Water Quantity:	60 cu.m/day	Quantity Allowable Domestic (cu.m)
	0 cu.m/day	Actual Quantity Used Domestic (cu.m)
	60 cu.m/day	Quantity Allowable Drilling (cu.m)
	0 cu.m/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No work was conducted during 2007, therefore no water was used and no waste deposited

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

There were no spills.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

To date there has been no reclamation work undertaken.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

Heeqou camp is located at: 112 degrees 44 minutes 42 seconds West Longitude, 65 degrees, 59 minutes, 2 seconds North Latitude.
No work was conducted, therefore no water was used in 2007

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

No work was conducted, therefore no waste was deposited in 2007

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Not applicable

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

April 18, 2008

Submitted/Prepared by:

David Ritcey, Senior Project Geologist, Diamondex Resources Ltd.

Contact Information:

Tel: (604) 687 6644

Fax: (604) 687 1448

email: dritcey@diamonex.net