

# WATER USE INSPECTION REPORT FORM

<b>Date:</b> July 8th, 2013	Licensee Rep. I	David Dehlin, Director
Licensee: Newmont Mining (	Corporation	Licence No: 2BE-HEN0508

**Comments**: An inspection was conducted Henik Lake Exploration Project. Due to the lack of annual reporting the project area was inspected using a spiral transect to cover the area of N61 39' 40.0" W98 06' 00.0" to N61 29' 45.45" W97 54' 00.0 which are considered to be the project boundaries.

### WATER SUPPLY

Source(s): N/A	<b>Quantity used:</b> N/A Allowed 60 cubic meters a day
Owner:/Operator: Newmont Mining Corporation	

Intake Facilities:
N/A

Storage Structure:
N/A

Treatment
Systems: N/A

Treatment
Systems: N/A

Chemical Storage:
N/A

Chemical Storage:
N/A

Pumping Stations:
N/A

Screen: N/A

Comments: This licence was issued for the purpose of drilling.

# WASTE DISPOSAL

**Comment:** No signs of waste or disturbance within claim extent.

Sewage: Sewage Treatment System: BIODISK

Natural Water Body: N/A		Continuous Discharge (land or water): N/A		
Seasonal Discharge: N/A		Wetlands Treatment: N/A		Trench: N/A
Indicate: <b>A</b> - Acceptable	<b>U</b> - Unaccep	otable <b>NA</b> - Not App	olicable <b>NI</b> - N	lot Inspected
Discharge Quality: N/A	Decant St	ructure: N/A	Erosion: N/A	Λ

Discharge Quality: N/A	Decant Structure: N/A	Erosion: N/A	
Discharge Meas. Device: N/A	Dyke Inspection: N/A	Seepages: N/A	
Dams, Dykes: N/A	Freeboard: N/A	Spills: N/A	
Construction: N/A	O&M Plan: N/A	A&R Plan: N/A	
Periods of Discharge: N/A	Effluent Discharge Rate: N/A		

**Comments:** Nueltin Fly-in Lodge was used as the base camp and staging area for this exploration project.

## **FUEL STORAGE:**

# Owner/Operator:

T 1' /	A , 1 1	<b>TT</b> TT	, 11	<b>TT A</b>	TAT / A 1' 11		TAT / T / 1
Indicate A	_ Accentable	11 _ 111	accentable	NΙΔ	- Not Anniicanie	N .	Not Inchected
mulcale. A	- ACCUDIADIC	<b>O</b> - OI	accentable	1177	- Not Applicable	141 -	mot madecica

Berms & Liners: N/a	Water within Berms: N/A	Evidence of Leaks: N/A	
Drainage Pipes: N/A	Pump Station & Catchments Berm: N/A		
Pipeline Condition: N/A	Condition of Tanks: N/A		

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Colle	ected	Owner / Operator: Newmont Canada	
0		AANDC:	
Signs Posted	SNP:		Warning: None
Records & Reporting: Annual Report submitted			
Geotechnical Inspection:			

#### **General Comments:**

• Over all very little was noted during the inspection with the exception of a few pieces of wood presumable steaks used during the exploration process.

#### Non-Compliance of Act or Licence:

- Part B item (1): Failure to pay water use fees
- Part B item (2): Failure to submit annual reports
- Part H item (1)(i-vii): Failure to submit addendum to Spill plan
- Part I item (1) and (2): Failure to revise and submit A&R plan

**Comments:** The Licensee shall contact the inspector upon receipt of the report by telephone at the coordinates listed below before Aug  $30^{th}$ , 2013.

All issues identified during this inspection have or will be address as discussed in this report.

Failure to undertake the actions required as described in this inspection report, and to the satisfaction of the Inspector, may result in enforcement action(s) being undertaken pursuant to the *Nunavut Waters and Nunavut Surface Rights Tribunal Act*.

Christine Wilson	Original signed on file
Inspector's Name	Inspector's Signature
Representative Name, Title	Representative Signature

Cc: Erik Allain- Manager Field Operations

Cc: Phyllis Beaulieu - Manager Licensing- Nunavut Water Board

Contact Information:
Christine Wilson
Resource Management Officer
Aboriginal Affairs and Northern Development Canada
Building 918 – Box 100
Iqaluit, Nunavut XOA OHO
867-975-4296 Ph
867-979-6445 Fx
Christine.Wilson@aandc.gc.ca