



*300-889 Harbourside Drive, North Vancouver, B.C. V7P 3S1  
phone 604-985-2572 fax 604-980-0731*

Stanley Anablak  
Kitikmeot Inuit Association  
PO Box 360  
Kugluktuk, NU X0B 0E0  
[sanablak@qinq.com](mailto:sanablak@qinq.com)

June 23, 2007

Re: Regional drilling program

Dear Mr. Anablak:

Our Regional Drilling program is getting underway testing targets away from our main work areas. Previously supplied work areas were best guesses as to where this work may be undertaken, at this time one area has been identified and confirmed for exploration drilling and as such MHBL would like to supply more detail as to how we think we can best operate in the area. The Main Area will receive at least four diamond drill holes testing subsurface targets. Water for this drilling will be obtained from the lake marked "primary water" on the accompanying map; if due to slow melting or other reasons this source is not acceptable we have indicated our alternate potential water sources.

Additionally, we would like to have a location in a suitable depression in a local outcrop cluster deemed acceptable for the deposition of drill cuttings. All of the cuttings will be collected at the individual drill sites using a Polydrill system, however, we would like to dispose of them at a single site generally identified on the accompanying map. Prior to drilling in the area the site will closely examined to make sure it is suitable and then clearly marked (see attached photos).

Regards,

***'signed'***

Darren Lindsay  
Exploration Manager  
Miramar Hope Bay Ltd.  
[dlindsay@miramarmining.com](mailto:dlindsay@miramarmining.com)

Photo of selected site located >1000m away from any body of water.



Arial view of sump site (black circle)



Local view of sump with large crack in outcrop



Close up of crack if drilling is close by.

