

WATER LICENCE INSPECTION FORM

\boxtimes	Original	
	Follow-Up	Repor

Licensee Licensee Representative											
Blue Star Gold Corp Darren Lindsay											
	Licence No. / Expiry Representative's Title										
2BE-HRP1924/14 July 2024 Vice-President, Exploration											
Land / Other Authorizations Land / Other Authorizations											
NIRB 19EA019											
Date of Inspection Inspector 11 August 2021 Baba Pedersen											
11 August 2021 Activities Inspected			вара Р	eaersen							
Camp	Псо	☐ Construction ☐ Reclamation ☐ Fuel Storage									
Roads/Hauling	Other:	Ot	her:								
Conditions: A - Acceptable C - Concern U - Unacceptable NA – Not Applicable NI – Not Inspected											
	•		- Unaccep			Not Applicab			•		
Water Use	Condition Comment					Haz/Mat M	lanagement	Condition	Comment		
Intake/Screen		Water Management Struc			Storage						
Flow Measure. Device		Culverts / Bridges				Spills					
Source:		Drainage				Spill Plan					
Water Use:		Erosion / Sediment									
Recirculation (y /n)		Mitigation Measures				Administra	tive				
() , ,		Reclamation Activi		Α	1	Records					
		Materials Storage		, · ·	_	Reports					
Waste Disposal						Plans					
-		Signage							1		
Waste Water							Notifications A				
Solid Waste		Monitoring				Other					
Hazardous Waste		Sample Collection	/ Analysis								
*Th	e number in the c	omments field will co	orrespond	with spec	ific comn	nents provide	d below.				
Samples taken by Inspector: Location(s):											
☐ Yes ☐ No		, ,									
SECTION 1	Comments (s)	Non-Cor	nnliance w	ith Δct ο	r Licence	(s)	Action R	equired (s)		
On Wednesday August 11, 2021, I, Baba Pedersen, Resource Management and Water Resource Officer with Crown-Indigenous Relations and Northern Affairs Canada, the Writer of this Report, did Inspect the Holder (Blue Star Gold Corporation) of Water											
License number 2BE-HRI			-				· -	-			
N 67* 15' and W 112* 2								pp. 0/a	,		
		_		al Ta:	a Dalk fua	46 - 1/:4:1	+ l:+ A				
I was accompanied in th	e nelicopter riyov	er inspection by wy	niter Biais a	ina ranni	S BOIL ITO	om the Kitikm	eot muit Ass	ociation			
SECTION 2	Comments	Non-Cor	npliance w	ith Act o	r Licence	Action R	tion Required				
This was a Fly-Over Insp	ection only of the	old Hood River Cam	p (Photos 1	to 3) tha	t has be	en previously	Cleaned up	Only Co	re		
Boxes and a Pile of Wooden Pallets remain on site.											
The Inspector requested that Blue Star remove all Wooden Pallets from the Hood River Camp Site.											
Unfortunately we were not able to visit any of the Activities under the Roma Gold Project at this time											
SECTION 3											
							_		wostod		
As per Photo #4 provided by Blue Star, the Inspector can confirm that Blue Star did indeed remove the Wooden Pallets as requested. Thank you very much. The Inspector has no further concerns at this time.											
Thank you very much. T	ne inspector has r	10 turtner concerns	at this time	!.							
Licensee or Representative	-	Inspector's Name									
Charles				Baba Pedersen							
Signature		Signature Signad Original on File									
Date		Signed Original on File									
		2021 December 10									
Office Use Only: Follow up report to be issued by Inspector											
Office Use Only: Follow-up report to be issued by Inspector											

cc. CIRNAC, Manager Field Operations, Iqaluit, <u>justin.hack@rcaanc-cirnac.gc.ca</u>

Nunavut Water Board, Manager of Licensing, Gjoa Haven, <u>licensing@nwb-oen.ca</u>



PHOTO LOG



Photo Log # DSCN0025

Photo 2

Description: Aerial View 2 of Old Hood River Camp







