



Separate from the above, the Licensee is reminded that the Board has not been in receipt of the required addenda to the Spill Contingency Plan and Abandonment and Restoration Plan, as included under Part H, Item 2 and Part I, Item 2, respectively, of Licence No. 2BE-HRP1416.

If you have any questions related to the above, please contact the NWB's Licensing Department at (867) 360-6368 or by email to [licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca).

Regards,

(for) Sean Joseph  
Technical Advisor

Cc: Kitikmeot Distribution List