

Suite 1125, 595 Howe Street, Vancouver, BC V6C 2T5 CANADA

Tel: +1.778.379.1433 Fax: +1.778.379.1434

7 October 2020

Manager of Field Operations, CIRNA Nunavut District, Nunavut Region P.O. Box 100 Igaluit, NU XOA 0H0

Dear Mr. Pedersen,

## Re. 2BE-HRP1924 Part H Item 4c – Spill Follow-up Report, October 2, 2020

Further to Part H Item 4c of 2BE-HRP1924, Blue Star Gold Corp. (Blue Star) is providing this letter in follow-up to a spill report submitted on October 2, 2020, and a follow-up spill report provided on October 7, 2020. The spill occurred in the Hood River camp, located at 111 °04′10.7" Long and 66°57′26.7" Lat.

The Hood River camp is comprised of a series of Weatherhaven-style tents. Tents are heated by stoves, which are connected to a drum of diesel located outside each tent. Each diesel drum is placed in a hard-sided secondary containment tray. At some point during camp operations, one of the trays started to leak, causing diesel to spill to the surrounding ground. This leak went undetected during camp operations as the contamination spread to the ground along the side of and underneath a tent platform. Accordingly, the quantity and time of the spill is unknown.

During camp demobilization in early October, the spill was detected, document and reported. Approximately 2 m³ of contaminated soil was excavated by hand, containerized, removed from site, and stockpiled within containment at Blue Star's adjacent Ulu Gold Project for treatment in the future Ulu soil treatment facility, licenced under 2BM-ULU2030.

I trust this satisfies the reporting required under this part. Should you require further information regarding this matter, please contact Sharleen Hamm at 604.996.1110 or Sharleen.hamm@bluestargold.ca.

Regards,

Peter Kuhn General Manager Blue Star Gold Corp.

Peter.kuhn@bluestargold.ca

778.379.1433

cc. W. Kuliktana, Kitikmeot Inuit Association

D. Donald, Nunavut Water Board